WELL PLUGGING RECORD STATE, OF KANSAS API NUMBER 15-145-6000 2 0007 K.A.R.-82-3-117 STATE CORPORATION COMMISSION 200 Colorado Derby Building LEASE NAME Benson Unit #202 : Wichita, Kansas 67202 WELL NUMBER TYPE OR PRINT NOTICE: Fill out completely SPOT LOCATION SW NE NW and return to Cons. Div. office within 30 days. SEC. 32 TWP. 23 SRGE. 15W(E) or (W) LEASE OPERATORKelso Casing bought f/ Cities Service Oil & Gas COUNTY Pawnee ADDRESS Box 347, Chase, Ks. 67524 Date Well Completed PHONE #(316) 938-2457 OPERATORS LICENSE NO. 6050 Plugging Commenced 12/28/85 Plugging Complèted 1/9/86 Character of Well (OII, Gas, D&A, SWD, Input, Water Supply Well) Did you notify the KCC/KDHE Joint District Office prior to plugging this well? Yes Which KCC/KDHE Joint Office did you notify? Dodge City Is ACO-1 filed? _____If not, is well log attached?___ Producing formation ______ Depth to top _____ bottom _______ T.D. 3938* Show depth and thickness of all water, oil and gas formations. OIL. GAS OR WATER RECORDS CASING RECORD Formation Content | From | To Size | Put in Pulled out 411 8 5/8 none 5/511 3937 _600 ' Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used state, the character of same and depth placed, from feet to feet each set. Plugged bottom with sand to 3500' & 5 sacks cement. Shot pipe at 2515', 2301', 1310', 907', 801', 724', 694', 655', & 600'. Pulled 19 joints of pipe. Plugged well with 2 hulls, 15 gel, 50 cement, 10 gel, 1 hull, 8 5/8 plug, & 150 sacks 60/40 poz 6% gel. Plugging complete. (If additional description is necessary, use BACK of this form.) Name of Plugging Contractor Kelso Casing Pulling Address Box 347, Chase, Ks. 67524 STATE OF Kansas COUNTY OF Rice R. Darrell Kelso (employee of operator) or (operator) of above-described well, being first duly sworn on oath, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-described well as filed that the same are true and correct, so help me God. (Signature) / / house

My Commission expires:

IRENE HOOVER
State of Kansas
My Appt. Exp. Aug. 15, 1989

STATE 20 310 - MA ISSIGN 2-14-86

(Address) Box 347, Chase, Ks. 67524

FFR 1 4 1986

Form CP-4 Revised 01-84

SUBSCRIBED AND SWORN TO before me thislithday of February , 1986

PLUGGING PROCEDURE FOR BENSON UNIT WELLS

- Dump sand of sufficient quantity to cover perforations fifty (50) feet.
- 2. Place five (5) sacks cement on sand using dump bailer prior to pulling pipe.
- 3. Run freepoint. Shoot off 5-1/2" casing and pull same.
- 4. Pump down 8-5/8" surface pipe as follows:
 - A. 3 sacks hulls
 - B. 50 sacks cement
 - C. 10 sacks gel
 - D. 30-50 sacks cement
 - E. 8 sacks gel
 - F. 1 sack hulls
 - G. 8-5/8" wiper plug
 - H. Appropriate volume of cement to fill surface pipe above plug (± 120 sacks)
- 5. Cut off 8-5/8" three (3) feet below ground level and verify surface casing is filled with cement.

The above procedure recommended by Paul Luthi of the Dodge City, Kansas Corporation Commission Office.

RECEIVED STATE CORPORATION COMMISSION

NOV 1 4 1985