

KCC OIL/GAS REGULATORY OFFICE

ATT. Jim H.
 New Situation
 Response to Request
 Follow-up

Date January 4, 2002

Operator Becker Oil Corporation # _____

Address _____ Location SE Sec 3, T 21 S, R 22

Lease Cox Well 1

Phone No. _____ County Hodgeman

Oper. _____ Other _____

Reason for Investigation: Finish top stage of well that did not circulate when completed. Did a log and found cement at 400'

Problem: _____

Person(s) Contacted: _____

Findings: Took an injection rate of 3 bbl. An minute at 350#. Mixed 50 sxs down backside and pressured to 500#. Shut down. Alt. II finished.

RECEIVED
KANSAS CORPORATION COMMISSION

JAN 08 2002

CONSERVATION DIVISION

photos taken: _____

Action/Recommendations: None have met all requirements .

- Lease Inspection
- Complaint
- Field Report

By Michael Maier

Retain 1 copy Joint District Office
Send one copy Conservation Division