STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely
Make Required Affidavit
Mail or Delive Report to:
Conservation Division
State Corporation Commission
212 No. Market

WELL PLUGGING RECORD

212 No. Market Wichita, Kansas			_ C	T			
NORTH		Location as "NE/CNW%SW%" or footage from lines NE SE SE Lease Owner Wayne E. Walcher & Petroleum, Inc. Lease Name Shuler Well No. 1 Office Address 808 Central Building, Wichita, Kansas					
	Office Address						
	· · · · · · · · · · · · · · · · · · ·	Vell (completed a			Dry Hole		
	Date well com	· -			December	13, ₁₉ 6	
1 1		plugging filed				10	
		plugging approv			December		
	Plugging comm	nenced			December	19	
	Plugging comp				<u>December</u>		
	Reason for aba	ndonment of well	or producing	g formation	<u>Dry Hole</u>		
	TE a mandancia d					19	
	_	well is abandone n obtained from		_		ore plugging was c	
Locate well correctly on above Section Plat	menced?	a obtained from	Yes Yes	(Gilbert	Toman of	Holyrood)	
me of Conservation Agent who	supervised plugging of th	is well					
oducing formation	J	Depth to top	Botton	0	Total Depth of	Well 3407 J	
ow depth and thickness of all v	water, oil and gas formatio	ns.					
OIL, CAS OR WATER REC	CORDS		,			CASING RECORI	
			<u> </u>			 	
FORMATION	Surface	FROM	243'	SIZE	PUT IN	PULLED OUT	
				8-5/8"	12/7/68		
	Casing	+ SIATE CO	RPORATION	ED			
·		<u> </u>	E O	ED COMMISSION		-	
		COMP	EC 1 8 1	60	- 1	 	
		QUIVSE!	VATION D hita, Kans	100			
		- YVIC	hita, Kans	VISION			
			14/13	42			
Describe in detail the mannintroducing it into the hole. I	If cement or other plugs w lug set. Heavy Mud f Plug and 25	rere used, state the rom Total sax Ceme	Depth	f same and dept to 235 F	h placed, from eet; 11 Pipe;		
introducing it into the hole. I	If cement or other plugs w lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly	rom Total sax Ceme eet; ½ sa and 10 sa	Depth nt thru x Hulls x Cemer	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F to the Dri	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs w lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat	Depth ent thru x Hulls x Cemer Hole.	to 235 F the Dri plug b to Bas	eet; 11 Pipe; pridged e of		
introducing it into the hole. I	If cement or other plugs we lug set. Heavy Mud for Plug and 25 Mud to 40 For with Kelly Cellar; 2 some 9:30 A.M.	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat 12/13/68	Depth ont thrux Hulls X Cemer Hole.	to 235 F the Dri s, Plug b to Bas Job Com	eet; 11 Pipe; pridged e of		
introducing it into the hole. I feet for each pi	If cement or other plugs we lug set. Heavy Mud for Pluq and 25 Mud to 40 For with Kelly Cellar; 2 some 9:30 A.M. Sage Drilli	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat 12/13/68	Depth nt thrux Hulls X Cemer Hole.	to 235 Far the Dris, Plug bat to Bas Job Com	eet; 11 Pipe; pridged e of		
introducing it into the hole. I feet for each pi	If cement or other plugs we lug set. Heavy Mud for Plug and 25 Mud to 40 For with Kelly Cellar; 2 some 9:30 A.M.	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat 12/13/68	Depth nt thrux Hulls X Cemer Hole.	to 235 Far the Dris, Plug bat to Bas Job Com	eet; 11 Pipe; pridged e of		
introducing it into the hole. I feet for each pi	If cement or other plugs we lug set. Heavy Mud for Pluq and 25 Mud to 40 For with Kelly Cellar; 2 some 9:30 A.M. Sage Drilli	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat 12/13/68	Depth nt thrux Hulls X Cemer Hole.	to 235 Far the Dris, Plug bat to Bas Job Com	eet; 11 Pipe; pridged e of		
introducing it into the hole. I feet for each pi	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s 9:30 A.M. Sage Drilli 500 Bitting	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat 12/13/68	Depth ont thrux Hulls X Cemer Hole.	to 235 Farthe Dris, Plug bat to Bas Job Com	h placed, from eet; 11 Pipe; pridged e of pleted		
introducing it into the hole. I feet for each pi	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s 9:30 A.M. Sage Drilli 500 Bitting	rom Total sax Ceme eet; sa and 10 sa ax in Rat 12/13/68 12/13/68	Depth ont thrux Hulls X Cemer Hole. Sary, use BACK nc. ichita,	to 235 Farthe Dris, Plug bat to Bas Job Com	h placed, from eet; 11 Pipe; ridged e of pleted	fee	
me of Plugging Contractor_dress	If cement or other plugs we lug set. Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s 9:30 A.M. Sage Drilli 500 Bitting er of Sage Dri	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat 12/13/68 12/13/68 I Bldg., W	Depth Int thru IX Hulls IX Cemer Hole. Ichita, DGWICK	to 235 Farthe Dris, Plug bat to Bas Job Com Tof this sheet) Kansas	h placed, from eet; 11 Pipe; pridged e of pleted , ss.	of the above-descr	
me of Plugging Contractor_dressATE OF KANSAS Wayne W. Kahmeye	Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s 9:30 A.M. Sage Drilli 500 Bitting or of Sage Dri path, says: That I have kr	rom Total sax Ceme eet; sa and 10 sa ax in Rat 12/13/68 12/13/68 In the same second control of the s	Depth ont thrux Hulls X Cemer Hole. ichita, DGWICK Employee of Cacts, stateme	to 235 Fathe Dris, Plug bat to Bas Job Com Tof this sheet) Kansas Downer) or (ownerts, and matter	h placed, from eet; 11 Pipe; pridged e of pleted , ss.	of the above-descr	
me of Plugging Contractor_dressATE OF KANSAS Wayne W. Kahmeye	Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s 9:30 A.M. Sage Drilli 500 Bitting or of Sage Dri path, says: That I have kr	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat 12/13/68 12/13/68 JNTY OF SE lling Coe cowledge of the ind correct. So h	Depth Int thru IX Hulls IX Cemer Hole. Ichita, DGWICK Employee of- facts, statemer elp me God.	to 235 Fathe Dris, Plug bat to Bas Job Com Tof this sheet) Kansas Downer) or (ownerts, and matter	h placed, from eet; 11 Pipe; pridged e of pleted , ss.	of the above-descr	
me of Plugging Contractor dress ATE OF KANSAS Wayne W. Kahmeye	Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s 9:30 A.M. Sage Drilli 500 Bitting or of Sage Dri path, says: That I have kr	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat 12/13/68 12/13/68 Interpretation is neces ing Co., I Bldg., W INTY OF SE lling Co. cowledge of the ind correct. So h (Signature)	Depth ont thrux Hulls X Cemer Hole. SHIP, USE BACK NC. ichita, DGWICK Employee of cats, statemer elp me God.	to 235 F the Dri s, Plug b t to Bas Job Com for this sheet) Kansas for this sheet Kansas	h placed, from eet; 11 Pipe; ridged e of pleted , ss. er or operator) s herein contain	of the above-descrated and the log of	
me of Plugging Contractor_dress ATE OF KANSAS Wayne W. Kahmeye	Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s 9:30 A.M. Sage Drilli 500 Bitting or of Sage Dri path, says: That I have kr	rom Total sax Ceme eet; ½ sa and 10 sa ax in Rat 12/13/68 12/13/68 Interpretation is neces ing Co., I Bldg., W INTY OF SE lling Co. cowledge of the ind correct. So h (Signature)	Depth ont thrux Hulls X Cemer Hole. SHIP, USE BACK NC. ichita, DGWICK Employee of cats, statemer elp me God.	to 235 Far the Dris, Plug bat to Bas Job Com Softhis sheet) Kansas Towner) or (owners, and matter Ling Bui	h placed, from eet; 11 Pipe; pridged e of pleted , ss. er or operator) s herein contain	of the above-descr	
me of Plugging Contractor_dress	Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s 9:30 A.M. Sage Drilli 500 Bitting er of Sage Dri bath, says: That I have ke	rom Total sax Ceme eet; sa and 10 sa ax in Rat 12/13/68 12/13/68 In Bldg., W JNTY OF SE lling Coe nowledge of the ind correct. So h (Signature)	Depth ont thrux Hulls X Cemer Hole. Sary, use BACK nc. ichita, DGWICK comployee of facts, statemed elp me God.	to 235 F the Dri s, Plug b t to Bas Job Com of this sheet) Kansas owner) or (own ents, and matter	h placed, from eet; 11 Pipe; ridged e of pleted , ss. er or operator) s herein contain	of the above-descrated and the log of	
me of Plugging Contractor_dress	Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s 9:30 A.M. Sage Drilli 500 Bitting er of Sage Dri bath, says: That I have ke	rom Total sax Ceme eet; sa and 10 sa ax in Rat 12/13/68 12/13/68 INTY OF SE 11ing Co to the find correct. So h (Signature)	Depth ont thrux Hulls X Cemer Hole. Sary, use BACK nc. ichita, DGWICK comployee of facts, statemed elp me God.	to 235 F the Dri s, Plug b t to Bas Job Com of this sheet) Kansas owner) or (own ents, and matter	h placed, from eet; 11 Pipe; pridged e of pleted , ss. er or operator) s herein contain	of the above-descrated and the log of	
me of Plugging Contractordress	Heavy Mud f Plug and 25 Mud to 40 F with Kelly Cellar; 2 s 9:30 A.M. Sage Drilli 500 Bitting er of Sage Dri bath, says: That I have ke	rom Total sax Ceme eet; sa and 10 sa ax in Rat 12/13/68 12/13/68 In Bldg., W JNTY OF SE lling Coe nowledge of the ind correct. So h (Signature)	Depth ont thrux Hulls X Cemer Hole. Sary, use BACK nc. ichita, DGWICK comployee of facts, statemed elp me God.	to 235 F the Dri s, Plug b t to Bas Job Com of this sheet) Kansas owner) or (own ents, and matter	h placed, from eet; 11 Pipe; pridged e of pleted , ss. er or operator) s herein contain	of the above-descrated and the log of	

ELEVATION: 1670KB

DRILLERS LOG

SHULER NO. 1

CASING RECORD: OPERATOR: Wayne E. Walcher & DESCRIPTION:
Petroleum, Inc.

8-5/8" @ 243'

w/175 sax cement CONTRACTOR: Sage Drilling Co.

COMMENCED: December 7, 1968

DESCRIPTION:
DESCRIPTION:
DESCRIPTION:
NE SE SE
Sec. 11-20S-9W
Rice County, Kansas

TOTAL DEPTH:

3407' COMPLETED: December 13, 1968

		. 	
FORMATION	FROM	TO	REMARKS
Surface Soil	0	245	STAR. D.
Shale & Shells	245	1085	STATE CONFORATION COMMISSION
Lime & Shale	1085	1730	D- RATION ED
Shale w/Lime Streaks	1730	2180	CONSERVATION ED Wichia, Kansas
Shale & Lime	2180	2495	Will Art of 19 Source
Lime & Shale	2495	3008	Wichita, Kansas SION
Lime	3008	3118	Mansa MSION
Lime & Shale	3118	3407	D&A

I certify that this is a true and correct copy of the above log to the best of my knowledge.

SAGE DRILLING CO., INC.

Wayne W. Kahmeyer

Splistribed and sworn to before me this 17th day of December, 1968.

Louise K. Whitted, Notary Public

My commission expires: November 26, 1970.