

1050521

To: STATE CORPORATION COMMISSION
CONSERVATION DIVISION - PLUGGING SECTION
200 COLORADO DERBY BUILDING
WICHITA, KANSAS 67202

API NUMBER 15- 187-20,390 .00.00

NW SE NE, SEC. 15, T 30 S, R 41 W/X

3380 feet from S section line

750 feet from E section line

TECHNICIAN'S PLUGGING REPORT

Operator License # 5363

Lease Name Gwinner "Z" Well # 2

Operator: Berexco, Inc.

County Stanton 182.33

Name & Address 970 Fourth Financial Center

Well Total Depth 5610 (Chester) feet

Wichita, KS 67202

Conductor Pipe: Size _____ feet

Surface Casing: Size 8 5/8 feet 1592

Abandoned Oil Well _____ Gas Well _____ Input Well _____ SWD Well _____ D&A X

Other well as hereinafter indicated _____

Plugging Contractor Beredco, Inc. License Number 5147

Address 401 E. Douglas, Suite 402, Wichita, KS 67202

Company to plug at: Hour: 10:00 am Day: 17 Month: May Year: 19 85

Plugging proposal received from Jim Long

(company name) Beredco (phone) 316-265-2856

were: to fill hole with heavy mud and spot cement through drill pipe Anhydrite 1590'
Elevation 3383'

1st plug at 1630' with 40 sx cement

2nd plug at 820' with 40 sx cement
solid bridge

3rd plug hulls - plug at 40' -- cement to surface with 10 sx cement

5th plug to circulate rat hole with 10 sx cement

6th plug to circulate mouse hole with 10 sx cement

Plugging Proposal Received by Richard W. Lacey
(TECHNICIAN)

Plugging Operations attended by Agent?: All _____ Part _____ None X

Operations Completed: Hour: 12:00 pm Day: 17 Month: May Year: 19 85

ACTUAL PLUGGING REPORT 1st plug at 1630' with 40 sx cement, 2nd plug at 820' with 40 sx

cement, 3rd & 4th plugs - solid bridge -hulls - plug at 40' -- cement to surface

with 10 sx cement, 5th plug to circulate rat hole with 10 sx cement, 6th plug to

circulate mouse hole with 10 sx cement.

RECEIVED
STATE CORPORATION COMMISSION
5-28-1985

MAY 28 1985

Remarks: Used 60/40 Pozmix 2% gel 3% cc by Halliburton CONSERVATION DIVISION

(If additional description is necessary, use BACK of this form Wichita, Kansas)

(I, Richard W. Lacey did not) observe this plugging.

Signed Richard W. Lacey
(TECHNICIAN)

DATE 5-29-85

INV. NO. 8287