

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Wm. Gruenerwald Address 35 East Wacker Drive, Chicago 1, Ill
(Applicant)

Lease (Farm Name) DEWELL Well No. 1

Well Location C SW 1 Sec. 28 Twp. 30S Rge. 41W (X) (W)

County Stanton Field Name (if any) _____

Total Depth 5512' Oil Gas Dry Hole Dry Hole

Was well log filed with application? Yes If not, explain: _____

Date and hour plugging is desired to begin _____ as soon as possible

Plugging of the well will be done in accordance with the Rules and Regulation of the
State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

Leonard G. Brock P.O. Box 134 Address Laverne, Oklahoma

Plugging Contractor Graham-Michaelis Drilling Company

Plugging Contractor's License No. _____

Address 211 North Broadway, Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Graham-Michaelis Drilling Co. Address 211 North Broadway, Wichita, Ks.

and payment will be guaranteed by applicant.

STATE CORPORATION COMMISSION

MAY 27 1957

CONSERVATION DIVISION
Wichita, Kansas

5/27/57

Graham Michaelis

Applicant or Acting Agent

Date May 16, 1957

PLUGGING			
FILE	SEC. <u>28</u>	T. <u>30</u>	R. <u>41W</u>
BOOK	PAGE <u>12</u>	LINE	<u>11</u>



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION

211 NORTH BROADWAY
WICHITA, KANSAS

May 13, 1957

Well No. 1
Lease Dewell
Description CSW 28-30-41N
County Stanton
File No. 12-11

William Grunerwald
c/o Graham-Michaelis Drlg. Co.
211 N. Broadway
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Dives, Box 6, Pratt, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY

S. S. Greider

WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor