

KANSAS
STATE CORPORATION COMMISSION

RECEIVED
STATE CORPORATION COMMISSION

JUN 14 1961

CONSERVATION DIVISION AGENT'S REPORT

TO:
Jewel M. Ogden, Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

CONSERVATION DIVISION
Wichita, Kansas

6-14-1961

File No. _____ County: Stanton

Location: C SW SW Sec. 13 Twp. 30 Rge. 41 (E) (W)

Name of Field: Banbury Total Depth: 5604

I have this date completed supervision of plugging of:

Lease Name: Banbury Well No. 1

Operator's Full Name: Felton Suband

Complete Address: Post Office Bldg, Tulsa, Okla.

Plugging Contractor: Controls

Address: _____ License No. _____

Oil Well _____ Gas Well _____ Input Well _____ SWD Well _____ D & A

Other well as hereafter indicated: _____

Was any delay in plugging operations caused by Conservation Division Agent? Yes _____ No

If yes how long? _____ Reason: _____

Operation Completed: Hour 10:00 Day 29 Month April Year 1961

The above well was plugged as follows:

1605' of 8 1/2" surface casing hole was filled to
1600' with heavy mud. Cement plug set at
1500' and 50' of cement was pumped in plug hole.
filled to 635' with heavy mud. Cement plug set
at 635'. 20' of cement was pumped in plug hole.
filled to 40' with heavy mud. Cement plug set at 40'.
10' of cement was pumped in plug hole.

Signed: [Signature]
Conservation Division Agent

Reviewed: [Signature]
Field Supervisor

Remarks:

INVOICED
DATE 6/29/61
INV. NO. 3312-u