

**KCC OIL/GAS REGULATORY OFFICES**

**Inspection Date:** 05/02/2018      **District:** 3      **Incident Number:** 6171

- New Situation       Lease Inspection
- Response to Request       Complaint
- Follow-up       Field Report

**Operator License No:** 30993      **API:** 15-001-29500-00-00 **Q3:** SE    **Q2:** SE    **Q1:** NW  
**Operator Name:** M.A.E. Resources, Inc.      **SEC** 24    **TWP** 23    **RGE** 19    **RGEDIR:** E  
**Address:** PO Box 304      **FSL:** 2815  
**City:** Parker      **FEL:** 2980  
**State:** KS      **Zip Code:** 66072      **Lease:** Curry      **Well No.:** 3-06  
**Phone contact:** (913) 898-3221      **County:** AL

**Reason for Investigation:**

Operator was going to plug two wells on the Curry lease located in Section 24, Towhship 23 South, Range 19 East, Allen County.

**Problem:**

Operator could only locate one of the wells.

**Persons contacted:**

Terry Johnson, Owner of M.A.E. Resources, 913-898-3221

**Findings:**

Arrived on site and witnessed the plugging of well #1-96, API #15-001-28697-00-00. After plugging the operator and I tried to locate well #3-06, API #15-001-29500-00-00. We went to the location where well #3-06 was suppose to be located and found an electrical post and riser. I used a metal detector and could not locate any well. Operator used a backhoe and dug down in the location where the well should have been. Operator dug down approximately 5' deep and approximately 10' by 20' and found no evidence of a well. No well could be located at this location.

**Actions / Recommendations**

**Follow-up Required**

**Deadline Date:**

Refer my findings to John Almond, District #3 Compliance officer, and after review of this field report forward this report to Wichita.

**Photo's Taken:** 0

- RBDMS     KGS     TA DB    **Report Prepared By:** Ryan Duling
- T1 DBF     District Files     Courthouse    **Position:** E.C.R.S.