

KCC OIL/GAS REGULATORY OFFICES

Date: 2-7-18

District: 1

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 6113
 Op Name: Landmark Resources Inc
 Address 1: 4900 Woodward Dr Ste 880
 Address 2: _____
 City: Houston
 State: Texas Zip Code: 77056
 Operator Phone #: 713 243-8550

API Well Number: 15-1712121800-00
 Spot: NW/NE Sec. 33 Twp 16 S Rng 34 E / W
335 Feet from N / S Line of Section
2023 Feet from E / W Line of Section
 GPS: Lat: _____ Long: _____ Date: _____
 Lease Name: Logan Well #: 1-33
 County: Scott

Reason for Investigation:

Alternate II Conty.

Problem:

Cement did not circulate on the production case.

Persons Contacted:

Findings:

8 7/8" @ 265', 5 1/2" @ 4856' w/ 150SK. DVU Tool @ 2440' w/ 375SK
TOC in annulus per temperature survey is 145'.
Ran 1" in the 5 1/2" x 8 7/8" annulus. Topped TOC @ 167'.
B-T services filled the annulus from 165' to 0' w/ 30SK Cement.

Action/Recommendations:

Follow Up Required Yes No

Date: _____

Alt II Conty Complete.

Verification Sources:

- RBDMS
- T-I Database
- Other: _____
- KGS
- District Files
- TA Program
- Courthouse

Photos Taken: _____

By: Ken Jehlik
ECB

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

RECEIVED
 FEB 13 2018
 KCC DODGE CITY

58

Form: _____