1 120898  TATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING EICHITA, KANSAS 67202		API NUMBER 15- 165-20,655 - 000		
		NE NE SE . SEC. 1		
				S section line
ECHNICIA	N'S PLUGGING REPORT			E section line
perator	License #	Lease Name Erbes	Kel	1 /
Necator:	AFG Energy Inc.	County Rush		2.10
•	P.O. Box 458	Well Total Depti		3634 )\b' foot
(441,435	Hays, KS 67601-0458	Conductor Pipe:		
		Surface Casing:	Size 8 5/8	teet 258
	Oll Well Gas WellX			
	•	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Other wel	li as bereinafter indicated			3232
Plugging	Contractor Lightning Well Servi	ce, Inc.	. License Num	Der
Liderace	P.O. Box 856, Russell, KS 67665			
	to plug at: Hour: 9:30 a.m. Day:	10 Month:	3	Year: 19 94
Company	proposal received from Terry P	iesker		
			(phon	913-625-6374
(company				
	at 3619 w/275 sx cement, PBTD 31	80', Peris at 3002-08	o , open noie	701.5 37
lst plug	fill 4½" with cement,			
2nd plug	g pump 125 sx cement down 8 5/8" X 43	∑" annulus.		
		oposal Recalved by	Richard La	acey
	Plugging Pr	oposa: Kecz: **** **/	(TEC	HNICIAN)
<b>-</b>	g Operations attended by Agent?:	All XPart		None
Pluggin	ons Completed: Hour: 1:30 p.m. Day		3	Year:19 <mark>94</mark>
Operati	ons Completed: Hour: 1.50 p.m. Day		EO are coment	with 200 lbs.
ACTUAL	PLUGGING REPORT 1st plug ran tubi	ng to 3006' and pumped	50 sx cement	WIEN ZOO IDG.
hulls,				
2nd plu	g pulled tubing to 1260' and circula	ted cement with 140 sx	ζ,	
3rd plu	g pulled all tubing and pumped in 8	5/8" X 4½" annulus wit	th 135 sx ceme	nt.
	pressure 0-400 psi and shut in 200			Dum.
Pumping	pressure 0-400 par and only		STATE	CORPORATION COMMISSION
			ATT	IAW ( C 45
Remark	used 60/40 Pozmix 6% gel by Alli	led. No casing recover	ACK of this	form.)
	(If additional description	12 Macassar 11 434 7	CONSE	RVATION DIVISION
i k Vla	V Orthogo Diserve this plugging	· //		chita, Konsas
		Signed	LECHNIC TECHNIC	AN)
DATE .	3-22-94 40126			FORM CP-
WA' MC	TUING			Rev. 01

## Erbes "A" #1

3-09-94

Moved in Rig. Rigged up. Ran tubing and changed out 65 collars. Pulled tubing out. Shut down. Tested tubing. 1 bad jt. - threads.

3-10-94

Ran tubing in to 3006'. Mixed 50 sxs. 60/40 Poz., 6% gel and 200# hulls. Pulled tubing up to 1260'. Circulated hole full with 140 sxs. 60/40 Poz., 6% gel. Cement circulated. Pulled tubing out of hole. Took off head and hooked to 8 5/8" casing. Mixed about 20 sx. 60/40 Poz. and 50# hulls and 4 1/2" began to circulate. Shut 4 1/2" Casing in and started mixing again. Mixed another 50# hulls and 105 sx. 60/40 Poz., - 6% gel. 50# on backside. Total 125 sx. down 8 5/8" casing.

