<u> </u>		0005		A D I N	UMBER 15-		17-0000	ı	
S1 C0	To: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202							R_21_W/6X	
20 ₩ (2310	feet fr	om Ss	ection line	
TE	TECHNICIAN'S PLUGGING REPORT				4290 feet from E section line				
01	Operator License # 9657			_ Lease	Name Str	odtman	Well #	1-3	
	perator:	O-1-6 Deba-1		- Count	у	Clark	_	171.28	
Al -	Namal	818 17th Street	, Suite 610					feet	
		Denver, CO 8020						e†	
			·		ce Casing				
At	bandoned	Oll Well X	Gas Well						
01	ther well	as hereinafter	indicated						
P	lugging C	ontractor Kelso	Casing Pulling	,		License	Number_	6050	
		P. O. Box 347,					_		
•		plug at: Hour:2			Month:	March	Year:	19_85	
			-					-	
	Plugging proposal received from Billy Faulds (company name) Kelso (phone) 316-938-2457								
	were: 4 1/2" set at 5274' PBTD 5231.07', Perfs at 5243-47'								
	1st plug sand back to 5190' and dump 4 sx cement on top of sand through bailer								
	2nd plug squeeze well with 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls,								
_		5/8" rubber plug	<u> — — — — — — — — — — — — — — — — — —</u>					 _	
_					 ;		<u> </u>	· · · · · · · · · · · · · · · · · · ·	
			Plugging Pro	onosal Rece	lved by	Paul A. 1	arthi		
_				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			ECHNIC I A	(N)	
P	lugging O	perations attend	ed by Agent?:	A1 IX	Part_	 -	None		
0	perations	Completed: Hou	r: 6:10 pm Day	12	Month:	March	Year:	19 85	
A	ACTUAL PLUGGING REPORT 1st plug sanded back to 5190' and dumped 4 sx cement on top								
<u>o f</u>	of sand through bailer, 2nd plug squeezed well with 3 sx hulls, 15 sx gel, 50 sx cement,								
<u>10</u>	10 sx gel, 1 sack hulls, released 8 5/8" rubber plug and pumped 150 sx cement.								
_						STATE CORPOR	GETVEU RATION COMMI	<u> 188101)</u>	
						ΜΛΩ	1 5 1005		
Ma	aximum pr	essure 400 psi a	nd shut in O			3-	15-85	- 	
	_	ecovered 4500' 4		Jsed 60/40	Pozmix 2%	gel 3%icki	กิโซเซ มเพราัสท g, Kby;aAll	ied	
	_	(If additiona	il description	ls necessar	y, use BA	CK of this	s form.)		
1 N [知数数数) observe	this plugging.	<	P	01	11	20	
	> 70	ره	•	Signe	od X as	TECHÁT	TAN	20	
10	1379	<u>)</u>						FORM CP-2/3	
	_	3-14				V. 2.5	•	Rev.01-84	