

CORR

Bramwell Petroleum, Inc.

Pt. 1, Box 2 A  
Spivey, Kansas 67142

April 10, 1992

Mr. Dennis Anderson  
Production Department  
Kansas Corporation Commission  
200 Colorado, Derby Bldg.  
202 W. 1st Street  
Wichita, Kansas 67202-1286

RE: Hanner #3  
API # 15-095-21657 - 00-00  
S1-30-7W

Dear Mr. Anderson,

In reference to your letter dated April 7, 1992, following is the information you have requested:

The formation drilled to, and to be produced out of is the Mississippi. It was encountered at 4094' and goes to below the TD.

As a result of BPI performing all aspects of the oilfield services when we are able, we did not hire a geologist. Therefore, we have no geologist well report.

If you require any further information, please feel free to call me at (316) 532-2770. I will make every attempt to supply the needed information.

Sincerely,

Douglas P. Bramwell /  
Douglas P. Bramwell  
Vice President  
Administrations  
*dm*

DPB/dm

4-15-92

RECEIVED  
STATE CORPORATION COMMISSION  
APR 15 1992  
CONSERVATION DIVISION  
WICHITA, KANSAS