TLOOP	NATER W	ell plu	gging record	Form WWC-5P	KSA 82a-1212	ID No.	AS-6
	ON OF WA	TER WEL	E Fraction		Section Number		Range Number
- County:	Sed	gwick	SW 1/4 N	W ¼ SW ¼	33	27	1E
Xetance :	and directi	on from n	earest town or city stre	et address of well if k	cated within city?		
*****			2160 S Broadway	y, Wichita, KS			
			count Cigarettes		Deser		
	Address, B s, ZIP Cod					of Agriculture, Division ation Number:	
MARK	Nell's loi	CATON W		35			·, · · · · · · · · · ·
']-х . ю s	ECTION BO	DX:		WELL 35			
X	N		WELL'S STA		19 r.		
			WELL WAS	used as:			
	;	i	1 Do	mentic 5 Pub	lic Water Supply	9 Dewsteri	ng
w		•	E 2 Irrig		ield Water Supply	10 Monitoria	*
					n and Garden (domesti		
X	sw		4 Ind	iustrial 8 Air (Conditioning	12 Other	
	·			bacteriological sample a			No
				sample was submitted			
	5		- Water Well Disini	lected: Yes	No		
TYPE	F BLANK C	ASING U			······································		
1 Stee		3 RMP		7 Fiberglass			
2PVC	; 		6 Asbestos-C in. Was casing p	Coment 8 Concrete 1	lite - Manada Indonesian		
					u yes, now m		
Casing h	wight above	woled to a	land surface	in.			
GROU	T PLUG MA	TERIAL:	1 Neat cement 2 Cer	ment grout (3)Be	ntonite 4 Othe	K	
Grout F	Nur Interval	e Fmm	ft. 10	• Emm	* *		
						ft. From	π. το. π.
vynet is						π. From	, п. ко w.
	the neeres		possible contamination:	a, ri y in	n. to	π. From	. n. to
1 Se) the neares ptic tank			(1)Fuel (torage	16 Other (specify b	
2 Se	ptic tank wer lines	t source oi	possible contamination:	(1)Fuel (
2 Se 3 Wa	ptic tank wer lines itertight sev	t source oi	f poesible contamination: 6 Seepage pit 7 Pit privy 8 Sewage legoon	(1) Fuel (12 Ferdii 13 Insec	torage zar storage licide storage		
2 Se 3 Wa 4 Lat	ptic tank wer lines stortight sew weral lines	t source oi	f possible contamination: 6 Seepage pit 7 Pit privy 8 Sawage legoon 9 Feedyard	(1) Fuel (12 Fertil 13 Insec 14 Aban	itorage zar storage ticide storage doned water well		
2 Ser 3 Wa 4 Lat 5 Ce	ptic tank wer lines tertight sew terai lines es Pool	t source ol rer linae	f possible contamination: 6 Seepage pt 7 Pit privy 8 Sewage lagoon 9 Feedyard 10 Livestook pans	(1) Fuel (12 Fertil 13 Insec 14 Aban 15 Off we	Korage Zer storage Licide storage Joned water well M/ Gas well	18 Other (specify b	
2 Ser 3 Wa 4 Lat 5 Ce	ptic tank wer lines tertight sew terai lines es Pool	t source ol rer linae	f possible contamination: 6 Seepage pit 7 Pit privy 8 Sawage legoon 9 Feedyard	(1) Fuel (12 Fertil 13 Insec 14 Aban 15 Off we	itorage zar storage ticide storage doned water well	18 Other (specify b	
2 Ser 3 Wa 4 Lat 5 Ce	ptic tank wer lines Hertight sew aral lines as Pool om well?	t source ol rer linae	Foesible contamination: 6 Seepage pit 7 Pit privy 8 Sewage lagoon 9 Feedyard 10 Livestook pans	(1) Fuel (12 Fertil 13 Insec 14 Aban 15 Off we	Korage Zer storage Licide storage Joned water well M/ Gas well	18 Other (specify b	
2 Ser 3 Wa 4 Lat 5 Ce frection fr	ptic tank wer lines hertight sew araí lines es Pool om weil? TO	t source ol rer lines	possible contaministion: 6 Seepage pit 7 Pit privy 8 Sewage lagoon 9 Feedyard 10 Livestock pans PLI	(1) Fuel (12 Ferdii 13 Insec 14 Aban 15 Oil we How many (UGGING MATERIALS	Korage Zer storage Licide storage Joned water well M/ Gas well	18 Other (specify b	
2 Set 3 Wa 4 Lat 5 Ce frection fr FROM 3	ptic tank wer lines nortight sew prai lines es Pool om well? <u>TO</u> 35	t source ol rer lines	peesible contamination: 6 Seepage pit 7 Pit privy 8 Sewage legoon 9 Feedyard 10 Livestock pans PLI Bentonite grout-	(1) Fuel (12 Ferdii 13 Insec 14 Aban 15 Oil we How many UGGING MATERIALS 30% solids	Korage Zer storage Licide storage Joned water well M/ Gas well	18 Other (specify b	
2 Ser 3 Wa 4 Lat 5 Ce frection fr	ptic tank wer lines hertight sew araí lines es Pool om weil? TO	t source ol rer lines	peesible contamination: 6 Seepage pit 7 Pit privy 8 Sewage legoon 9 Feedyard 10 Livestock pans PLI Bentonite grout-	(1) Fuel (12 Ferdii 13 Insec 14 Aban 15 Oil we How many (UGGING MATERIALS	Korage Zer storage Licide storage Joned water well M/ Gas well	18 Other (specify b	
2 Set 3 Wa 4 Lat 5 Ce frection fr FROM 3	ptic tank wer lines nortight sew prai lines es Pool om well? <u>TO</u> 35	t source ol rer lines	peesible contamination: 6 Seepage pit 7 Pit privy 8 Sewage legoon 9 Feedyard 10 Livestock pans PLI Bentonite grout-	(1) Fuel (12 Ferdii 13 Insec 14 Aban 15 Oil we How many UGGING MATERIALS 30% solids	Korage Zer storage Licide storage Joned water well M/ Gas well	18 Other (specify b	
2 Set 3 Wa 4 Lat 5 Ce frection fr FROM 3	ptic tank wer lines nortight sew prai lines es Pool om well? <u>TO</u> 35	t source ol rer lines	peesible contamination: 6 Seepage pit 7 Pit privy 8 Sewage legoon 9 Feedyard 10 Livestock pans PLI Bentonite grout-	(1) Fuel (12 Ferdii 13 Insec 14 Aban 15 Oil we How many UGGING MATERIALS 30% solids	Korage Zer storage Licide storage Joned water well M/ Gas well	18 Other (specify b	
2 Set 3 Wa 4 Lat 5 Ce Prection fr FROM 3	ptic tank wer lines nortight sew prai lines es Pool om well? <u>TO</u> 35	t source ol rer lines	peesible contamination: 6 Seepage pit 7 Pit privy 8 Sewage legoon 9 Feedyard 10 Livestock pans PLI Bentonite grout-	(1) Fuel (12 Ferdii 13 Insec 14 Aban 15 Oil we How many UGGING MATERIALS 30% solids	Korage Zer storage Licide storage Joned water well M/ Gas well	18 Other (specify b	
2 Set 3 Wa 4 Lat 5 Ce Prection fr FROM 3	ptic tank wer lines nortight sew prai lines es Pool om well? <u>TO</u> 35	t source ol rer lines	peesible contamination: 6 Seepage pit 7 Pit privy 8 Sewage legoon 9 Feedyard 10 Livestock pans PLI Bentonite grout-	(1) Fuel (12 Ferdii 13 Insec 14 Aban 15 Oil we How many UGGING MATERIALS 30% solids	Korage Zer storage Licide storage Joned water well M/ Gas well	18 Other (specify b	
2 Set 3 Wa 4 Lat 5 Ce Prection fr FROM 3	ptic tank wer lines nortight sew prai lines es Pool om well? <u>TO</u> 35	t source ol rer lines	peesible contamination: 6 Seepage pit 7 Pit privy 8 Sewage legoon 9 Feedyard 10 Livestock pans PLI Bentonite grout-	(1) Fuel (12 Ferdii 13 Insec 14 Aban 15 Oil we How many UGGING MATERIALS 30% solids	Korage Zer storage Licide storage Joned water well M/ Gas well	18 Other (specify b	
2 Set 3 Wa 4 Lat 5 Ce krection fr FROM 3 0	ptic tank wer lines nertight sew prai lines es Pool om well? 35 3	t source of rer lines	possible contaministion: 6 Seepage pit 7 Pit privy 8 Sewage lagoon 9 Facelyard 10 Livestock pans PLI Bentonite grout- Ni	(1) Fuel (12 Fertil 13 Insec 14 Aban 15 Oil we How many (UCGING MATERIALS 30% solids ative materials	Norage zar storage kicke storage koned water well ki/ Gas well ket?	16 Other (specify b	Nêi(TW)
2 Ser 3 Wa 4 Lat 5 Ce birection fr FROM 3 0	ptic tank wer lines tertight sew prai lines es Pool om well? 35 3 3	t source of rer lines	possible contaministion: 6 Seepage pit 7 Pit privy 8 Sewage lagoon 9 Facelyard 10 Livestock pans PLI Bentonite grout- Ni NOOWNER'S CERTIFIC	(1) Fuel (12 Fertil 13 Insec 14 Aban 15 Oil we How many (UGGING MATERIALS 30% solids ative materials ATION: This water we	torage zar storage tode storage tode torage tode water well by/ Gas well leet?	16 Other (specify b	xeicw)
2 Ser 3 Wa 4 Lat 5 Ce birection fm FROM 3 0 CON ort (1	ptic tank wer lines tertight sew prai lines es Pool om well? 35 3 3 	source of rer lines	possible contamination: 6 Seepage pit 7 Pit privy 8 Sewage legoon 9 Feedyard 10 Livestook pans PLI Bentonite grout- Ni NOCWINER'S CERTIFIC 8/30/11	(1) Fuel (12 Fertil 13 Insec 14 Aban 15 Oil we How many (UGGING MATERIALS 30% solids ative materials ATION: This water we	torage zar storage boned water well bl/ Gas well teet? 	16 Other (specify b	xeicw)
2 Ser 3 Wa 4 Lat 5 Ce birection fm FROM 3 0 CON ort (1	ptic tank wer lines tertight sew prai lines es Pool om well? 35 3 3 	s or LAi	possible contaministion: 6 Seepage pit 7 Pit privy 8 Sewage legoon 9 Feedyard 10 Livestock pans PLI Bentonite grout- Ni NDOWNER'S CERTIFIC 8/30/11 License No.	(1) Fuel of 12 Fertili 13 Insect 14 Aband 15 Oil we How many f UCGING MATERIALS 30% solids ative materials ATION: This water well and this	torage zer storage toned water well bl/ Gas well leet? 	16 Other (specify b	eicw) completed and belief. Kanaza d on (mo/day/yr)
2 Set 3 Wat 4 Lat 5 Ce birection fm FROM 3 0 CON on (i Wat	ptic tank wer lines sertight sew prai lines es Pool om well? 35 3 3 	t source of rer lines CODE	Possible contamination: 6 Seepage pit 7 Pit privy 8 Sewage legoon 9 Feedyard 10 Livestook pans PLI Bentonite grout- Na NOOWNER'S CERTIFIC 8/30/11 License No. under the busi	(1) Fuel of 12 Fertili 13 Insect 14 Aband 15 Oil we How many f UGGING MATERIALS 30% solids ative materials ATION: This water well and this ness name of	torage zer storage toned water well bl/ Gas well leet? 	16 Other (specify b	eitow) completed and belief. Kanaza d on (mo/day/yr)
2 Ser 3 Wa 4 Lat 5 Ce FROM 3 0 CON on (1 Wath by	ptic tank wer lines tentight sew prai lines es Pool om well? TO 35 3 3 1 1 1 TRACTOR mo/day/yr) sr Well Co 9/ (signeture)	source of rer lines CODE	possible contaministion: 6 Seepage pit 7 Pit privy 8 Sewage legoon 9 Feedyard 10 Livestock pans PLI Bentonite grout- Ni NDOWNER'S CERTIFIC 8/30/11 License No.	(1) Fuel of 12 Fertili 13 Insect 14 Aband 15 Oil we How many f UCGING MATERIALS 30% solids ative materials ATION: This water well and this mass name of	torage zar storage toned water well bl/ Gas well leet? 	16 Other (specify b 	completed and belief. Kanasa d on (mo/day/yr) . Inc.