1 LOCATI	5		WATER	R WELL RECORD F	orm WWC-5	KSA 82a	1212		
<u> </u>	ON OF WAT	ER WELL:	Fraction		Sec	tion Number	Township Numb	er	Range Number
County:	Cowley		SE 1/4	NW ¼ NE		19	T 33	S R	4 EW
Distance a	and direction	from nearest town	or city street ad	dress of well if located	within city?				•
2 m	iles N (	of Ark. City	at Stroth	er Field Indus	trial Pa	irk			
2 WATER	R WELL OW	NER: Gener	al Electri						
_	Address, Bo			Industrial Par	k. P.O.	Box 797	Board of Agric	ulture, Divisio	n of Water Resource
	, ZIP Code			Kansas 67005		2011 737	Application Nu		
				OMPLETED WELL					
AN "X"	IN SECTION								
	1	1 10	epth(s) Groundw	vater Encountered 1.	19	measur	jng point · · · ·	π. 3	π. 5 /14 /85
Ī	<u> </u>			WATER LEVEL19.					
·	- NW	_ X <sub>NE</sub>	•	test data: Well water					
	1	, <u> </u>     E		gpm: Well water					
<u>.</u>	i	I B	lore Hole Diamet	ter 9 <del></del> 5/8in. to .	29.5	ft., a	ınd	in. to .	
Mile M	1	ı "v	VELL WATER TO	D BE USED AS: 5	Public wate	r supply	8 Air conditioning	11 Jnjecti	on well
- 1		1	1 Domestic	3 Feedlot 6	Oil field wat	ter supply	9 Dewatering 0 Observation well	Other	(Specify below)
	SW	SE	2 Irrigation	4 Industrial 7	Lawn and g	arden only (1	Observation well	Monit	<del>oring</del>
	! !	:     w	Vas a chemical/h	acteriological sample su	bmitted to De	epartment? Ye	s No X	: If ves. mo/d	av/vr sample was sub
į L			nitted	actoriological campio ca			er Well Disinfected?		
F TYPE	OF DI ANIX (	ASING USED:		E Wrought iron	8 Concre				Clamped
	_			5 Wrought iron					
1 Ste		3 RMP (SR)		6 Asbestos-Cement		(specify below			
<b>2</b> PV	/C	4 ABS		7 Fiberglass					
				ft., Dia					
Casing he	ight above la	and surface	24	in., weight			t. Wall thickness or g	auge No ⊱	schedule.40
TYPE OF	SCREEN O	R PERFORATION	MATERIAL:		7)PV	C	10 Asbesto	s-cement	
1 Ste	eel	3 Stainless s	steel	5 Fiberglass	8 RM	IP (SR)	11 Other (:	specify)	
2 Bra	ass	4 Galvanized	d steel	6 Concrete tile	9 AB	S	12 None u	sed (open ho	le)
SCREEN (	OR PERFOI	RATION OPENING	S ARE:	5 Gauzeo	wrapped		8 Saw cut	11 1	None (open hole)
	ontinuous slo			6 Wire w	rapped		9 Drilled holes		
	uvered shut		punched	7 Torch o	• •		10 Other (specify) .		
		ED INTERVALS:		.7.•.Q ft. to					
SCHEEN-I	PENFORATI	ED INTERVALS.		ft. to					
	004451 04	OK INTERVALO							
		CK INTERVALS:		.50 ft. to					
		Collapse			29.5			π. το	ft.
	T MATERIAL			2 Cement grout					
		nO ft	. to 15•C	) ft., From	. , ft. '	to	ft., From		to
What is th	e nearest so								
1 0-		ource of possible co	ontamination:			10 Livest	<b>F</b>		ned water well
1 56	eptic tank		ontamination:	7 Pit privy			ock pens storage	15 Oil well	/Gas well
	eptic tank ewer lines	ource of possible co	ontamination: lines			11 Fuels	<b>F</b>	15 Oil well 16 Other (	/Gas well specify below)
2 Se	ewer lines	ource of possible co 4 Lateral	ontamination: lines ool	7 Pit privy		11 Fuel s 12 Fertilia	storage	15 Oil well 16 Other (	/Gas well
2 Se	ewer lines atertight sew	ource of possible co 4 Lateral 5 Cess p	ontamination: lines ool ge pit	7 Pit privy 8 Sewage lagoo		11 Fuel s 12 Fertilia	storage zer storage icide storage	15 Oil well 16 Other (	/Gas well specify below)
2 Se 3 Wa	ewer lines atertight sew	ource of possible co 4 Lateral 5 Cess p er lines 6 Seepag	ontamination: lines ool ge pit	7 Pit privy 8 Sewage lagoo 9 Feedyard		11 Fuel s 12 Fertiliz 13 Insect	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other (	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM	ewer lines atertight sew from well?	urce of possible co 4 Lateral 5 Cess p er lines 6 Seepag all around	ontamination: lines ool ge pit	7 Pit privy 8 Sewage lagoo 9 Feedyard	on	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0	ewer lines atertight sew from well? TO 0.5	urce of possible of 4 Lateral 5 Cess p er lines 6 Seepag all around	ontamination: lines ool ge pit LITHOLOGIC L	7 Pit privy 8 Sewage lagod 9 Feedyard	on	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM	ewer lines atertight sew from well? TO 0.5	urce of possible co 4 Lateral 5 Cess p er lines 6 Seepag all around Topsoil Dark brown	ontamination: lines ool ge pit LITHOLOGIC L silty clay	7 Pit privy 8 Sewage lagoo 9 Feedyard	on	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5	rewer lines atertight sew from well?  TO  0.5  2.5	urce of possible co 4 Lateral 5 Cess p er lines 6 Seepag all around Topsoil Dark brown moist, stif	ontamination: lines ool ge pit LITHOLOGIC L silty clay	7 Pit privy 8 Sewage lagoo 9 Feedyard OG 7, trace sand,	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0	rewer lines atertight sew from well?  TO  0.5  2.5	urce of possible co 4 Lateral 5 Cess p er lines 6 Seepag all around Topsoil Dark brown moist, stif Brown silty	ontamination: lines ool ge pit LITHOLOGIC L silty clay	7 Pit privy 8 Sewage lagod 9 Feedyard	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5	ewer lines atertight sew from well? TO 0.5 2.5	aurce of possible co 4 Lateral 5 Cess p er lines 6 Seepag all around Topsoil Dark brown moist, stif Brown silty stiff	ontamination: lines ool ge pit LITHOLOGIC L silty clay if clay, tra	7 Pit privy 8 Sewage lagor 9 Feedyard  OG 7, trace sand, ace sand, moist	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5	ewer lines atertight sew from well? TO 0.5 2.5	aurce of possible co 4 Lateral 5 Cess p er lines 6 Seepag all around Topsoil Dark brown moist, stif Brown silty stiff Gray-brown	ontamination: lines ool ge pit LITHOLOGIC L silty clay if clay, tra silty clay	7 Pit privy 8 Sewage lagoo 9 Feedyard OG 7, trace sand,	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5	ewer lines atertight sew from well? TO 0.5 2.5	aurce of possible co  4 Lateral  5 Cess p er lines 6 Seepag all around  Topsoil Dark brown moist, stif Brown silty stiff Gray-brown moist, stif	ontamination: lines ool ge pit LITHOLOGIC L silty clay f clay, tra silty clay	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  7, trace sand, ace sand, moist 7, trace sand,	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5	ewer lines atertight sew from well? TO 0.5 2.5	Topsoil Dark brown moist, stiff Gray-brown moist, stiff Red-brown &	ontamination: lines ool ge pit LITHOLOGIC L silty clay f clay, tra silty clay	7 Pit privy 8 Sewage lagor 9 Feedyard  OG 7, trace sand, ace sand, moist	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5	ewer lines atertight sew from well? TO 0.5 2.5 7.5	Topsoil Dark brown moist, stiff Gray-brown moist, stiff Red-brown & stiff	ontamination: lines ool ge pit LITHOLOGIC L silty clay f clay, tra silty clay f gray sand	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  The trace sand, ace sand, moist The trace sand, ace sand, ace sand, ace sand,	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5	ewer lines atertight sew from well? TO 0.5 2.5 7.5	Topsoil Dark brown moist, stiff Gray-brown moist, stiff Red-brown &	ontamination: lines ool ge pit LITHOLOGIC L silty clay f clay, tra silty clay f gray sand	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  The trace sand, ace sand, moist The trace sand, ace sand, ace sand, ace sand,	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5 7.5	wer lines atertight sew from well?  TO  0.5  2.5  7.5  12.5  17.5	Topsoil Dark brown moist, stiff Gray-brown moist, stiff Red-brown & stiff	ontamination: lines ool ge pit LITHOLOGIC L silty clay f clay, tra silty clay f gray sand	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  The trace sand, ace sand, moist The trace sand, ace sand, ace sand, ace sand,	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5 7.5 12.5 17.5	wer lines atertight sew from well?  TO  0.5  2.5  7.5  12.5  17.5	aurce of possible co  4 Lateral  5 Cess p er lines 6 Seepag all around  Topsoil Dark brown moist, stif Brown silty stiff Gray-brown moist, stif Red-brown & stiff Brown fine	ontamination: lines ool ge pit LITHOLOGIC L silty clay f clay, tra silty clay f gray sand	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  The trace sand, ace sand, moist The trace sand, ace sand, ace sand, ace sand,	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5 7.5 12.5 17.5	wer lines atertight sew from well?  TO  0.5  2.5  7.5  12.5  17.5	aurce of possible co  4 Lateral  5 Cess p er lines 6 Seepag all around  Topsoil Dark brown moist, stif Brown silty stiff Gray-brown moist, stif Red-brown & stiff Brown fine	ontamination: lines ool ge pit LITHOLOGIC L silty clay f clay, tra silty clay f gray sand	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  The trace sand, ace sand, moist The trace sand, ace sand, ace sand, ace sand,	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5  2.5  7.5  12.5	wer lines atertight sew from well?  TO  0.5  2.5  7.5  12.5  17.5	aurce of possible co  4 Lateral  5 Cess p er lines 6 Seepag all around  Topsoil Dark brown moist, stif Brown silty stiff Gray-brown moist, stif Red-brown & stiff Brown fine	ontamination: lines ool ge pit LITHOLOGIC L silty clay f clay, tra silty clay f gray sand	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  The trace sand, ace sand, moist The trace sand, ace sand, ace sand, ace sand,	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5 7.5 12.5 17.5	wer lines atertight sew from well?  TO  0.5  2.5  7.5  12.5  17.5	aurce of possible co  4 Lateral  5 Cess p er lines 6 Seepag all around  Topsoil Dark brown moist, stif Brown silty stiff Gray-brown moist, stif Red-brown & stiff Brown fine	ontamination: lines ool ge pit LITHOLOGIC L silty clay f clay, tra silty clay f gray sand	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  The trace sand, ace sand, moist The trace sand, ace sand, ace sand, ace sand,	FROM	11 Fuel s 12 Fertiliz 13 Insect How man	storage zer storage icide storage y feet? 100 '	15 Oil well 16 Other ( INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5 7.5 12.5	rower lines atertight sew from well? TO 0.5 2.5 7.5 12.5 17.5 29.5 Total	aurce of possible co  4 Lateral  5 Cess p er lines 6 Seepag all around  Topsoil Dark brown moist, stif Brown silty stiff Gray-brown moist, stif Red-brown & stiff Brown fine Depth	ontamination: lines ool ge pit LITHOLOGIC L silty clay if clay, tra silty clay if gray sand sand, wet,	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  7, trace sand, 1 ce sand, moist 7, trace sand, 1 dense	FROM	11 Fuel s 12 Fertiliz 13 Insect How man TO	storage zer storage icide storage y feet? 100 ' LIT!	15 Oil well 16 Other (: INdustri	/Gas well specify below) .al .Activity
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5 7.5 12.5	rower lines atertight sew from well? TO 0.5 2.5 7.5 12.5 17.5 29.5 Total	aurce of possible co  4 Lateral  5 Cess p  er lines 6 Seepag  all around  Topsoil  Dark brown  moist, stif  Brown silty  stiff  Gray-brown  moist, stif  Red-brown S  stiff  Brown fine  Depth	contamination: lines lines cool ge pit LITHOLOGIC L silty clay if clay, tra silty clay if gray sand sand, wet,	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  7, trace sand, ace sand, moist 7, trace sand, by silt, moist, dense  ON: This water well was	FROM  FROM  Construction	11 Fuel s 12 Fertiliz 13 Insect How man TO	storage zer storage icide storage by feet? 100 '  LIT!	15 Oil well 16 Other (s INdustri HOLOGIC LC	/Gas well specify below) .al.Activity  OG  / jurisdiction and was
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5 7.5 12.5 17.5 29.5	rower lines atertight sew from well? TO 0.5 2.5 7.5 12.5 17.5 29.5 Total	aurce of possible co  4 Lateral  5 Cess p er lines 6 Seepag all around  Topsoil Dark brown Moist, stiff Brown silty stiff Gray-brown Moist, stiff Red-brown & stiff Brown fine Depth  DR LANDOWNER'S	contamination: lines cool ge pit LITHOLOGIC L silty clay f clay, tra silty clay f gray sand sand, wet,	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  7, trace sand, ace sand, moist 7, trace sand, dy silt, moist, dense	FROM  FROM  (1) construction	11 Fuel s 12 Fertiliz 13 Insect How man TO	storage zer storage icide storage by feet? 100 '  LIT!	15 Oil well 16 Other (s INdustri HOLOGIC LC	/Gas well specify below) .al.Activity  OG  / jurisdiction and was ge and belief. Kansas
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5 7.5 12.5 17.5 29.5	rower lines atertight sew from well? TO 0.5 2.5 7.5 12.5 17.5 29.5 Total	A Lateral 5 Cess per lines 6 Seepage all around Topsoil Dark brown moist, stiff Brown silty stiff Gray-brown moist, stiff Red-brown & stiff Brown fine Depth  DR LANDOWNER'S (year) S License No.	contamination: lines lin	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  7, trace sand, ace sand, moist 7, trace sand, dy silt, moist, dense  ON: This water well was	FROM  FROM  (1) construction	11 Fuel s 12 Fertiliz 13 Insect How man TO  cted, (2) record and this record s completed of	storage zer storage icide storage ly feet? 100 '  LIT!	15 Oil well 16 Other (s INDUSTRIAL HOLOGIC LO	/Gas well specify below) .al.Activity  OG  / jurisdiction and was ge and belief. Kansas
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5 7.5 12.5 17.5 29.5	rower lines atertight sew from well?  TO  0.5  2.5  7.5  12.5  17.5  29.5  Total  RACTOR'S (I on (mo/day)) II Contractor business na	A Lateral 5 Cess per lines 6 Seepage all around Topsoil Dark brown moist, stiff Brown silty stiff Gray-brown moist, stiff Red-brown & stiff Brown fine Depth  OR LANDOWNER'S (year)  S License No The stiff in the	contamination: lines lines cool ge pit LITHOLOGIC L silty clay if clay, tra silty clay if gray sand sand, wet, 5/8/85 102 -Western C	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  7, trace sand, ace sand, moist 7, trace sand, dy silt, moist, dense  ON: This water well was  This Water Well Company, Inc.	FROM  FROM  (1) construction	11 Fuel s 12 Fertiliz 13 Insect How man TO  cted, (2) record and this record s completed of by (signat	nstructed, or (3) plugged is true to the best on (ne/day/yr)	ged under my f my knowled 6/15/85	/Gas well specify below) .al.Activity  OG  / jurisdiction and was ge and belief. Kansas
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5 7.5 12.5 17.5 29.5	rower lines atertight sew from well?  TO  0.5  2.5  7.5  12.5  17.5  29.5  Total  RACTOR'S (I on (mo/day)) II Contractor business na itions: Use	all around  Topsoil Dark brown moist, stif Brown silty stiff Gray-brown moist, stiff Red-brown & stiff Brown fine Depth  DR LANDOWNER'S (year) s License No. me of Layne typewriter or ball po	contamination: lines lin	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  7, trace sand, ace sand, moist 7, trace sand, dy silt, moist, dense  ON: This water well was This Water Well Company, Inc. EPRESS FIRMLY and	FROM FROM III Construction III Record was PRINT clearly	11 Fuel s 12 Fertiliz 13 Insect How man TO  cted, (2) record and this record s completed complet	nstructed, or (3) plugged is true to the best on (ne)day/yr) ure) United in the best of th	ged under my f my knowled 6/15/85	/Gas well specify below) .al.Activity  OG  / jurisdiction and was ge and belief. Kansas  containswers. Send top
2 Se 3 Wa Direction f FROM 0.0 0.5 2.5 7.5 12.5 17.5 29.5 7 CONTECT Completed Water Well under the INSTRUC three copies	rom well? TO 0.5 2.5 7.5 12.5 17.5 12.5 17.5 17.5 19.5 Total	all around  Topsoil Dark brown moist, stif Brown silty stiff Gray-brown moist, stiff Red-brown & stiff Brown fine Depth  DR LANDOWNER'S (year) s License No. me of Layne typewriter or ball po	ontamination: lines line	7 Pit privy 8 Sewage lagor 9 Feedyard  OG  7, trace sand, ace sand, moist 7, trace sand, dy silt, moist, dense  ON: This water well was  This Water Well Company, Inc.	FROM FROM III Construction III Record was PRINT clearly	11 Fuel s 12 Fertiliz 13 Insect How man TO  cted, (2) record and this record s completed complet	nstructed, or (3) plugged is true to the best on (ne)day/yr) ure) United in the best of th	ged under my f my knowled 6/15/85	/Gas well specify below) .al.Activity  OG  / jurisdiction and was ge and belief. Kansas  County answers. Send top