

CORRECTION(S) TO WATER WELL RECORD (WWC-5)

(to rectify lacking or incorrect information)

Location listed as:

Section-Township-Range: 27-24S-36W

Fraction ($\frac{1}{4}$ $\frac{1}{4}$ $\frac{1}{4}$): SE SW NE

County: Kearny

Location changed to:

27-24S-36W

W2 SE NW NE

Other changes: Initial statements: _____

Changed to: _____

Comments: Believed to be the well that is labeled "Existing
Well" on attached map.

verification method: Attached site location map, and mapping tool
on KGS website.

initials: DRL date: 9/18/2007

submitted by: Kansas Geological Survey, Data Resources Library, 1930 Constant Ave., Lawrence, KS 66047-3726

to: Kansas Dept of Health & Environment, Bureau of Water, 1000 SW Jackson, Suite 420, Topeka, KS 66612-1367.

 $\frac{1}{4}$

Henkle

DRILLING & SUPPLY CO., INC.

3795 W. JONES AVE.
316/277-2389
FAX/277-0224

P.O. Box 639
GARDEN CITY, KANSAS 67846

CUSTOMER'S NAME Servi-Tech (Farmers Coop Lakin) DATE June 13, 1990
STREET ADDRESS 710 W. Trail TEST # 2 E. LOG _____
CITY & STATE Dodge Ciyt, Kansas 67801 DRILLER Wildeman
COUNTY Kearny QUARTER _____ SECTION _____ TOWNSHIP _____ RANGE _____
LOCATION 5' east of teat #1 at Lakin Coop

[illegible]

