

County: Sedgwick Fraction: SW, SW, SE, SE Sec. 13 T. 26 S R. 1 W

**CORRECTION(S) to WATER WELL COMPLETION RECORD Form WWC-5 (to rectify lacking or incorrect information)**

Owner: Mies Construction Dewatering

If location corrected, was listed as:

Location changed to:

Section-Township-Range: \_\_\_\_\_

\_\_\_\_\_

Fraction (1/4 calls): \_\_\_\_\_

\_\_\_\_\_

Other changes: Initial statements: 'Other' accidentally selected as a source of contamination, typed words 'None within 200ft' are a typo.

Changed to: \_\_\_\_\_

Comments: Nearest source of possible contamination is 'Watertight Sewer Lines'.

Verification method: Confirmed w/ Alex Olmso.

Submitted by: \_\_\_\_\_ Initials: BA Date: 05/19/2023

Kansas Geological Survey, Data Resources Library, 1930 Constant Ave., Lawrence, KS 66047-3724

Kansas Dept. of Health & Environment, Bureau of Water, 1000 SW Jackson, Suite 420, Topeka, KS 66612-1367

