



Pioneer Energy Services

Dual Compensated Porosity Log

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments

Thank you for using Log-Tech, Inc.
(785) 625-3858


Ellis.


North to county line (EE Rd), 2 West to Co. Rd 1, 1 1/4 North,
East and South to location


Database File: vess_082112hd.db
Dataset Pathname: dil/vstack
Presentation Format: cdl
Dataset Creation: Tue Aug 21 20:54:43 2012
Charted by: Depth in Feet scaled 1:600

0	Gamma Ray	150
6	Caliper (GAPI)	16

30	Compensated Density				-10
2	Bulk Density				3
15000	Line Tension				0
2.625	DGA	3.425	-0.25	Correction	0.25
					LSPD







Database File:

vess_082112hd.db

Dataset Pathname:

dil/vstack

Presentation Format:

cnlspec

Dataset Creation:

Tue Aug 21 20:54:43 2012

Charted by:

Depth in Feet scaled 1:240

0	Gamma Ray	150	30	CNLS			-10	
6	Caliper (GAPI)	16	30	Compensated Density (2.71 ma)			-10	
			2.625	DGA	3.425	-0.25	Correction	0.25
			10000	Line Tension				0
								LSPD

