



Dual Compensated Porosity Log

Pioneer Energy Services

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments


Thank you for using Pioneer Energy Services
www.pioneerres.com
785 625 3858


Medicine Lodge KS, South to Sumac RD,
1 3/4 West, 1/4 NorthEast, South Into


Database File: c:\warrior\data\val_pyle no. 5-3\val_pyle_5_3hd.db
Dataset Pathname: DIL\valstk
Presentation Format: cdl
Dataset Creation: Wed Sep 19 13:59:44 2012
Charted by: Depth in Feet scaled 1:600

Charted by: Depth in Feet scaled 1:600

0	Gamma Ray	150	30	Compensated Density		-10
6	Caliper (GAPI)	16	2	Bulk Density		3
			15000	Line Tension		0
			2.625	DGA	3.425	-0.25
			Correction			0.25
						LSPD







6	Caliper (GAPI)	16

2	Bulk Density		3
15000	Line Tension		0
2.625	DGA	3.425	-0.25
			Correction
			0.25
			LSPD

Database File: c:\warrior\data\val_pyle no. 5-3\val_pyle_5_3hd.db										
Dataset Pathname: DIL\valstk										
Presentation Format: cndlspec										
Dataset Creation: Wed Sep 19 13:59:44 2012										
Charted by: Depth in Feet scaled 1:240										
0			Gamma Ray				150			
6			Caliper (GAPI)				16			
30			Compensated Neutron (Limestone)				-10			
30			Compensated Density (Limestone)				-10			
2.625			DGA		3.425		-0.25		Correction	0.25
15000			Line Tension				0			

