



Dual Compensated Porosity Log

Pioneer Energy Services

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.


Comments


Thank you for using Pioneer Energy Services
www.pioneerres.com
785 625 3858

Lenora KS, W on Hwy 9 to W15Ln Rd,
N, W Into

Database File: c:\warrior\data\murfin_ryser #1-24\murfhd.db
Dataset Pathname: dil\murfstk
Presentation Format: cdl
Dataset Creation: Wed May 29 09:06:36 2013
Charted by: Depth in Feet scaled 1:600

Charted by: _____ Depth in Feet scaled 1:600					
0	Gamma Ray	150	30	Compensated Density	-10
6	Caliper (GAPI)	16	2	Bulk Density	3
			15000	Line Tension	0
			-0.25 Correction 0.25		
			LSPD		





Database File: c:\warrior\data\murfin_ryser #1-24\murfhd.db
 Dataset Pathname: dil/murfstk
 Presentation Format: cndlspec
 Dataset Creation: Wed May 29 09:06:36 2013
 Charted by: Depth in Feet scaled 1:240

