



Pioneer Energy Services

Borehole Compensated Sonic Log

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments

Thank you for using Pioneer Energy Services
www.pioneerres.com
785 625 3858

McDonald, 12 North to BB Road, 1 1/2 East, 1/4 South, 1/4 East

Database File: c:\warrior\data\berexco_michael # 3-22\berexco_michael_3-22hd.db
Dataset Pathname: rag/berrag
Presentation Format: sonic
Dataset Creation: Fri Oct 04 07:11:38 2013
Charted by: Denth in Feet scaled 1:240

Charted by:		Depth in Feet scaled 1:210						
0	Gamma Ray	150	Sonic Int	140	Delta Time (usec/ft)	40		
150	Gamma Ray	300		5	0	30	SPOR	-10
Caliper					15000	LTEN (lb)	0	
						LSPD		











































