



Pioneer Energy Services

Dual Compensated Porosity Log

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments


Thank you for using Pioneer Energy Services
www.pioneerres.com
785 625 3858


Dighton KS, 1 1/2 W S Into between buildings

Database File	larson_meeker #1 owwo\larshd3.db
Dataset Pathname	dil\larstk2
Presentation Format	cdl
Dataset Creation	Tue Mar 03 15:41:50 2015
Charted by	Depth in Feet scaled 1:600

0	Gamma Ray	150
6	Caliper (GAPI)	16

30		Compensated Density		-10	
2		Bulk Density		3	
15000		Line Tension		0	
2.625	DGA	3.425	-0.25	Correction	0.25
					LSPD





Database File	larson_meeker #1 owwo\larshd3.db
Dataset Pathname	dil\larstk2
Presentation Format	cnldspec
Dataset Creation	Tue Mar 03 15:41:50 2015
Charted by	Depth in Feet scaled 1:240

0	Gamma Ray	150	30	Compensated Neutron (Limestone)	-10
6	Caliper (GAPI)	16	30	Compensated Density (Limestone)	-10

15000	Line Tension			0
2.625	DGA	3.425	-0.25	Correction 0.25
				LSPD

