

KANSAS CORPORATION COMMISSION 1026733 OIL & GAS CONSERVATION DIVISION

Form CDP-1 April 2004 Form must be Typed

APPLICATION FOR SURFACE PIT

Submit in Duplicate

Operator Name:			License Number:	
Operator Address:				
Contact Person:			Phone Number:	
Lease Name & Well No.:			Pit Location (QQQQ):	
Type of Pit:	Pit is: Proposed Existing If Existing, date constructed:		 SecTwpR Feet from [East West
Uvorkover Pit Haul-Off Pit (If WP Supply API No. or Year Drilled)	Pit capacity: (bbls)			East / West Line of Section
Is the pit located in a Sensitive Ground Water Area? Yes No		Chloride concentration: mg/l (For Emergency Pits and Settling Pits only)		
Is the bottom below ground level?	Artificial Liner?		How is the pit lined if a plastic liner is not used?	
Pit dimensions (all but working pits):	Length (feet)		Width (feet)	N/A: Steel Pits
Depth from ground level to deepest point: (feet) No Pit				
Distance to nearest water well within one-mile of pit		Source of infor		feet. electric logKDWR
Emergency, Settling and Burn Pits ONLY:		Drilling, Workover and Haul-Off Pits ONLY:		
Producing Formation:	Type of material utilized in drilling/workover:			
Number of producing wells on lease:		Number of working pits to be utilized:		
Barrels of fluid produced daily:	Abandonment procedure:			
Does the slope from the tank battery allow all flow into the pit? Yes No	Drill pits must be closed within 365 days of spud date.			
Submitted Electronically				
KCC OFFICE USE ONLY Steel Pit RFAC RFAS				
Date Received: Permit Num	ber:	Permi	t Date: Lea	ase Inspection: 🗌 Yes 🗌 No

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202



March 05, 2009

Bryan Hess Hess Oil Company PO BOX 1009 MCPHERSON, KS67460-1009

Re: Workover Pit Application FRITZLER Lease Well No. 1-8 Sec.08-21S-21W Hodgeman County, Kansas

Dear Bryan Hess:

District staff has inspected the location and has determined that an unsealed condition will present a pollution threat to water resources.

District staff has recommended that the Workover pit be lined. If a plastic liner is to be used it must have a minimum thickness of 10 mil. Integrity of the liner must be maintained at all times.

NO completion fluids or non-exempt wastes shall be placed in the Workover pit.

The free fluids in the Workover pit should be removed as soon as practical after drilling operations have ceased. The fluids should be taken to an authorized disposal well. Please call the District Office at (620) 225-8888 when the fluids have been removed. Please file form CDP-5 (August 2004), Exploration and Production Waste Transfer, within 30 days of fluid removal. Conservation division forms are available through our office and on the KCC web site: kcc.ks.gov/conservation/forms/

If you have any questions or concerns please feel free to contact the District Office at (620) 225-8888.