

Miami County, KS  
 Well:Boyscout F2-10  
 Lease Owner:Bobcat

Town Oilfield Service, Inc.  
 (913) 837-8400

Commenced Spudding:  
 9/27/2010

WELL LOG

Thickness of Strata	Formation	Total Depth
2	Soil	2
8	Clay	10
7	Shale	17
28	Lime	45
2	Shale	47
9	Lime	56
2	Shale	58
13	Lime	71
85	Shale	156
18	Lime	174
2	Shale	176
8	Sand	184-Gray, No Bleed
2	Lime	186
22	Shale	208
6	Lime	214
32	Shale	246
9	Lime	255
3	Shale	258
4	Lime	262
12	Shale	274
26	Lime	300-Winterset
8	Shale	308
22	Lime	330-Bethany Falls
4	Shale	334
4	Lime	338-KC
4	Shale	342
6	Hertha	348-Lime
140	Shale	488
3	Sand	491-Odor, Little Show, Gray
5	Sand	496-Good Show
2	Sand	498-Gray
5	Shale	503
5	Lime	508
66	Shale	574
3	Lime	577
46	Shale	623
2	Lime	625
1	Shale	626
4	Lime	630
6	Shale	636

