



BASICSM
ENERGY SERVICES
PRESSURE PUMPING & WIRELINE

1700 S. Country Estates Rd.
P.O. Box 129
Liberal, Kansas 67905
Phone 620-624-2277

FIELD SERVICE TICKET
1717 01042 A

DATE _____ TICKET NO. _____

DATE OF JOB 9-14-10 DISTRICT 1717		NEW WELL <input checked="" type="checkbox"/> OLD WELL <input type="checkbox"/> PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/> CUSTOMER ORDER NO.:				
CUSTOMER Oxy USA		LEASE W.E. Preedy		WELL NO. 6		
ADDRESS		COUNTY Haskell		STATE Ks		
CITY		STATE		SERVICE CREW Cochran/Gibson/S. Chavez		
AUTHORIZED BY		JOB TYPE: Z42 5 1/2 L.S.				
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED 9-13 AM 12:30
21955	13					ARRIVED AT JOB 9-13 AM 15:30
27808	13					START OPERATION 9-14 AM 01:30
19553	13					FINISH OPERATION 9-14 AM 08:00
33021	13					RELEASED 9-14 AM 04:30
33016	13					MILES FROM STATION TO WELL 35

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: *W. E. Preedy*
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
CL100	Premium	SK	50		800 00
CL104	50/50 Poz	SK	205		2255 00
CC113	Gypsum	lb	865		648 75
CC111	Salt	lb	1120		560 00
CC124	FLA-115	lb	109		1560 00
CC107	C-42P	lb	44		352 00
CC201	Gilsonite	lb	1024		686 08
146 CF1561	507 Fract	ea	10		
CF1651	Turbolizer	ea	35		3850 00
CF103	Top Plug	ea	1		105 00
CF267	Guide shoe	ea	1		250 00
CF501	Stop Ring	ea	1		40 00
CC155	Super Flush	gal	500		765 00
E101	Heavy Equip Mileage	Mi	100		700 00
CE240	Blending & Mixing Serv: Chrg.	SK	265		357 00
E113	Bulk Delivery	Ton	550		880 00
CE206	Depth Chrg. 5001'-6000'	Yhr	1		2880 00
CE504	Plug Container	job	1		250 00
E100	Pick-up Mileage	Mi	50		212 50

SUB TOTAL **12093 80**

CHEMICAL / ACID DATA:			

SERVICE & EQUIPMENT	%TAX ON \$	
MATERIALS	%TAX ON \$	
TOTAL		

SERVICE REPRESENTATIVE *Pick Cochran* THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: *W. E. Preedy*

FIELD SERVICE ORDER NO. _____

(WELL OWNER OPERATOR CONTRACTOR OR AGENT)

Customer	Oxy USA	Lease No.		Date	9-13-10
Lease	W. E. Preedy	Well #	6		
Field Order #	171701042	Station	Liberal	Casing	5 1/2
				Depth	5695
Type Job	292 5 1/2 L.S.	Formation		County	Haskell
				State	Ks
				Legal Description	JJ 29.33

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME	
Casing Size	Tubing Size	Shots/Ft	205 sk 50150 Per-5 1/2 w-10	Rate	PRESS	ISIP	
Depth	Depth	From	.67 To C-15	Max	5" Dilsonite	5 Min.	
Volume	Volume	From	1.58 #1 1/2" Per 6.65 gal/sk @ 13.8 #/gal	Min		10 Min.	
Max Press	Max Press	From	50 sk Premium - Next for Rst + Mouse	Max		15 Min.	
Well Connection	Annulus Vol.	From	1.18 #3/8" 5.22 gal/sk	HH Used	@ 15.6 #/gal	Annulus Pressure	
Plug Depth	Packer Depth	From		Flush		Total Load	
		To		Gas Volume			

Customer Representative	A. Hanson	Station Manager	J. Bennett	Treater	M. Cochran
-------------------------	-----------	-----------------	------------	---------	------------

Service Units	21755	27804	19053	37020	33016				
Driver Names	Cochran	Gibson	S. Chvacek						

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
15:30					on loc. / Held Safety Meeting
17:00					Start Csg.
23:00					Csg on Bottom Cir. w/ Rig
01:40	2500				Test Pump + Lines
01:42	700		5	5	Start Fresh H ₂ O
01:43	300		12	5	Start Super Flush II
01:46	300		5	5	Start Fresh H ₂ O
01:47					Shutdown + Switch to Rattle + Mouse Hole
01:51	100		1R 3m	2	Plug R.H. w/ 25 sk / Plug Mouse w/ 25 sk
02:00					Switch Back to Pipe
02:02	450		55	5-2	Start Cmt 205 sk @ 13.8 #
02:25					Shutdown + Wash up
02:27					Drop Plug
02:32	150		0	6-5	Start Disp. w/ Fresh H ₂ O
02:53	750		121	2	Slow Rate
02:54	1400		131	2	Bump Plug
02:58	0		131	0	Release / Float Held
03:00					End Job
	900				Pressure Before Plug Landed
					Lost Returns for 3-4 min. when
					Spacers Turned Corner