



BASICSM
ENERGY SERVICES
PRESSURE PUMPING & WIRELINE

1700 S. Country Estates Rd.
P.O. Box 129
Liberal, Kansas 67905
Phone 620-624-2277

FIELD SERVICE TICKET
1717 01092 A

DATE _____ TICKET NO. _____

DATE OF JOB <u>9/24/10</u>	DISTRICT <u>1717</u>	NEW WELL <input checked="" type="checkbox"/>	OLD WELL <input type="checkbox"/>	PROD <input type="checkbox"/>	INJ <input type="checkbox"/>	WDW <input type="checkbox"/>	CUSTOMER ORDER NO.:	
CUSTOMER <u>Oxy USA</u>		LEASE <u>McMillan "B"</u>					WELL NO. <u>1</u>	
ADDRESS		COUNTY <u>Morton</u>			STATE <u>KS</u>			
CITY		SERVICE CREW <u>Royce R. Martinez, Victor</u>						
AUTHORIZED BY <u>Tyce Davis</u>		JOB TYPE: <u>5/8 Surface E42</u>						
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	TIME
<u>19588</u>	<u>4.5</u>	<u>19578</u>	<u>4.5</u>					<u>9:00</u>
<u>30463</u>	<u>4.5</u>					ARRIVED AT JOB		<u>11:43</u>
<u>19543</u>	<u>4.5</u>					START OPERATION		<u>1:53</u>
<u>19527</u>	<u>4.5</u>					FINISH OPERATION		<u>3:27</u>
<u>19566</u>	<u>4.5</u>					RELEASED		<u>4:30</u>
<u>14354</u>	<u>4.5</u>					MILES FROM STATION TO WELL		<u>65</u>

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: P.M. Wyl
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

~~1108~~ 1105080-0202

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
CL101	A-Con Blend	SK	480		8928 00
CL110	Premium Plus	SK	200		3260 00
CC109	Calcium Chloride	lb	1732		1818 60
CC102	Celloflake	lb	291		1076 70
CC130	C-51	lb	91		2275 00
CF1453	Flapper Float Valve 5 5/8"	EA	1		280 00
CF253	Guide Shoe 5 5/8"	EA	1		380 00
CF1793	Centralizer 5 5/8"	EA	5		725 00
CF1903	5 5/8" Basket	EA	1		315 00
E101	Heavy Equip Mileage	mi	195		1365 00
CE240	Blending & mixing Charge	SK	680		952 00
CF105	TOP Plug 5 5/8"	EA	1		225 00
E113	Bulk Delivery Charge	Tm	3,080		3328 00
CE202	Depth Charge 1001' to 2000'	4hr	1		1500 00
CE504	Plug Container	Job	1		250 00
E100	Pickup Mileage	mi	65		276 25
5003	Service Super U1302	EA	1		175 00
SUB TOTAL					<u>16,566.48</u>

CHEMICAL / ACID DATA:			

SERVICE & EQUIPMENT	%TAX ON \$	
MATERIALS	%TAX ON \$	
TOTAL		

SERVICE REPRESENTATIVE <u>Chad Hinz</u>	THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY <u>P.M. Wyl</u>
---	--

(WELL OWNER OPERATOR CONTRACTOR OR AGENT)

FIELD SERVICE ORDER NO.

Customer Oxy USA	Lease No.	Date 9/24/10
Lease McMillan "B"	Well # 1	
Field Order #	Station Liberal	Casing 4 5/8" Depth 1743' County Morton State KS
Type Job 8 5/8" surface	Formation	Legal Description 13-32-40

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME	
Casing Size 4 5/8"	Tubing Size	Shots/Ft		Acid 2450 SKS A-Con	RATE 320 gal/sk	PRESS 14 #	ASYP Cellflake - 2% W/O
Depth 1736.74'	Depth	From	To	Pre Pad 2.41 cuft/sk	Max 14.00 gal/sk @ 12.1 #		
Volume 107.66	Volume	From	To	Post 300 SKS Prem Plus	Min 1.34 cuft/sk	10 Min.	33 gal/sk
Max Press 1000 #	Max Press	From	To	Fract 2% CaCl₂, 1/4 # Cellflake		15 Min.	
Well Connection P.C.	Annulus Vol.	From	To		HHP Used		Annulus Pressure
Plug Depth	Packer Depth	From	To	Flush Fresh	Gas Volume		Total Load

Customer Representative Cal Wylie	Station Manager Serry Bennett	Treater Chad Hinz
Service Units 19586 30463 19843 19827 19566 14354 19578		
Driver Names Chinz R. Olds R. Martinez V. Vasquez		

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
11:43					on loc, spot Equip, safety mtg, Rig up
13:00					safety mtg, Break Circ
13:53	2500 #				Psi test
13:57	250 #		0	4.8	Start mix A-Con @ 12.1 #
14:35	250 #		206	4.8	switch to tail @ 14.8 #
14:47	100 #		46	4	Finish mixing
14:50	0		48	-	Shutdown, drop plug
14:57	0		0	4	Start disp, washup on plug
15:21	500 #		90	2	slow rate
15:27	600 # - 1000 #		104	0	Plug down
15:28	1000 - 0				Release Psi float held.
					Job Complete
					Thank You
					Chad & Crew