

Mike's Testing & Salvage Inc.

P O Box 467
Chase, KS 67524

Invoice

Date	Invoice #
4/21/2011	12715

Bill To
American Energies Corp P O. Box 3972 Wichita, Kansas 67201-03972

5097

P O. No	Lease	County
	Stucky C 1	McPherson

Qty	Description	Rate	Amount
14	Hours Rig Time	190.00	2,660.00T
	Casing Cutter	250.00	250.00T
4	Sacks Cement	12.50	50.00T
	Sand	40.00	40.00T
4 14 11	Rigged up on location. 1 Hour		
4-18 11	Checked the hole, sanded off bottom to 3070' and 4 sacks cement on top Dug cellar and pit, set in floor and rigged up, had 5" of stretch Cut pipe loose @835' pulled up to 400' 9 Hours		
4-19 11	Rigged up Copeland Cementers, pumped 275 sacks @400' lost circulation, Rigged down. 4 Hours		
4-21-11	Ran poly pipe to 280' tagged cement, pumped 140 sacks cement and circulated to surface. Plugging Complete. 4 Hours.		
	Sales Tax	7.30%	219.00
		Total	\$3,219.00

COPELAND

POST OFFICE BOX 438
 HAYSVILLE, KS 67060
 (316) 524-1225
 (316) 524-1027 FAX

Invoice

Page: 1

Acid & Cement

BURRTON, KS ♦ GREAT BEND, KS
 (620) 463-6161 (620) 793-3366
 FAX (620) 463-2104 FAX (620) 793-3536

INVOICE NUMBER:
C37668-IN

BILL TO:

AMERICAN ENERGIES CORP.
 P.O. BOX 516
 CANTON, KS 67428

LEASE: STUCKEY C 1

DATE	ORDER	SALESMAN	ORDER DATE	PURCHASE ORDER	SPECIAL INSTRUCTIONS	
04/27/2011	C37668		04/21/2011		NET 30	
QUANTITY	U/M	ITEM NO./DESCRIPTION		D/C	PRICE	EXTENSION
1.00	EA	CEMENT PUMP CHARGE		0.00	600.00	600.00
140.00	SAX	60-40 4% POZ MIX		0.00	9.69	1,356.60
1.00	EA	POLY TRAILER		0.00	200.00	200.00
1.00	MI	CEMENT MILEAGE PUMP TRUCK		0.00	3.00	3.00
140.00	EA	BULK CHARGE		0.00	1.25	175.00
1.00	MI	MIN. BULK TRUCK - TON MILES		0.00	150.00	150.00
REMIT TO: P.O. BOX 438 HAYSVILLE, KS 67060		COP-B		Net Invoice:		2,484.60
RECEIVED BY _____		FUEL SURCHARGE IS NOT TAXABLE AND IS ADDED TO MILEAGE, PUMP AND OR DELIVERY CHARGES ONLY.		MCPCO Sales Tax:		58.40
		NET 30 DAYS		Invoice Total:		<u>2,543.00</u>

There will be a charge of 1.5% "per month" (18% annual rate) on all accounts over 30 days past due.

Copeland Acid & Cement is a subsidiary of Gressel Oil Field Service

Gressel Oil Field Service reserves a security interest in the goods sold until the same are paid for in full and reserve all the rights of a secured party under the Uniform Commercial Code

RECEIVE:

NO. 4408

04/27/2011/WED 10:40AM



TREATMENT REPORT

Acid Stage No.

Date: 4/21/11 District: Arkansas P. O. No.
 Company: American Energy Corp
 Well Name & No.: Stacking 278
 Location: _____ Field: 2
 County: McPherson State: Ks

Casing: Size _____ Type & Wt. _____ Set at _____ ft.
 Formation: _____ Perf. _____ to _____
 Formation: _____ Perf. _____ to _____
 Formation: _____ Perf. _____ to _____
 Liner: Size _____ Type & Wt. _____ Top at _____ ft. Bottom at _____ ft.
 Cemented: Yes/No. Perforated from _____ ft. to _____ ft.
 Tubing: Size & Wt. _____ Spuns at _____ ft.
 Perforated from _____ ft. to _____ ft.

Well Hole Size: _____ T.D. _____ ft. P.U. to _____ ft.

Type Treatment: Amt. _____ Type Fluid _____ Sand Size _____ Pounds of Mud _____

Blowdown: _____ Bbl./Gal. _____
 _____ Bbl./Gal. _____
 _____ Bbl./Gal. _____
 _____ Bbl./Gal. _____

Flush: _____ Bbl./Gal. _____

Treated from _____ ft. to _____ ft. No. ft. _____
 from _____ ft. to _____ ft. No. ft. _____
 from _____ ft. to _____ ft. No. ft. _____

Actual Volume of (Oil/Water) to Load Hole: _____ 10 (Bbl./Gal.)

Pump Trucks: No. Used: 303 Hrs. _____ Twin _____
 Auxiliary Equipment: Poly Pipe to 280' Bulk tank 302
 Packer: _____ Set at _____ ft.
 Auxiliary Tools _____
 Plugging or Sealing Materials: Type: 140 sacks 60-40-4²

Company Representative _____

Treater: My R

TIME a.m /p.m.	PRESSURES		Total Fluid Pumped	REMARKS
	Tubing	Casing		
1:45				On location with Poly trailer & Pump Truck
1:50				Do ISA rig up Poly Trailer
2:10				Run Poly pipe down Stack out 280'
2:15				Try to work pipe on Down Hit Hard 280'
2:20				Rig up to mix cement
2:45			0	Water on location tie on Poly pipe start water
2:50			10 Bbl.	To load Hole located shut down for cement
3:10			27 1/2 Bbl.	Cement on location start mix Start shuck down hole at 1:30m. Good cement to surface 140 sacks mixed & okay pull out poly pipe wash up in cellar. Leave down a bit location