
Form CP-111 March 2009 Form must be Typed Form must be signed

## TEMPORARY ABANDONMENT WELL APPLICATION

All blanks must be complete

OPERATOR: License#					API No. 15-  Spot Description:													
											Address 1:					•		R 🗆 E 🔲 W
Address 2:					feet from N / S Line of Section													
City:	State:	Zip: +					E / ☐W Line of Section											
Contact Person: Phone:( ) Contact Person Email: Field Contact Person: Field Contact Person Phone:( )					GPS Location: Lat:													
											Spud Date: Date Shut-In:							
												Conductor	Surface	Pr	oduction	Intermediate	Liner	Tubing
											Size							
											Setting Depth							
					Amount of Cement													
Top of Cement																		
Bottom of Cement																		
Do you have a valid Oil & G.  Depth and Type:  Junk i  Type Completion:  ALT.  Packer Type:  Total Depth:	n Hole at IALT. II Depth o Size:	Tools in Hole at — f: DV Tool:	epth) w /	sack	s of cement Port	Collar: w /												
Geological Data:																		
Formation Name	Formation	Formation Top Formation Base			Completion Information													
1	At:	to l				Feet or Open Hole Interv												
2	At:	to I	Feet Perfo	oration Interval	to F	Feet or Open Hole Interv	ral toFeet											
		Subn	nitted Ele	ectronicall	у													
Do NOT Write in This Space - KCC USE ONLY				Date Plugged: Date Repaired: Date Put Back in Service:														
Review Completed by:	Review Completed by: Comn			ments:	ents: TA Approved: Yes Denied Denied													
		Mail to the		KCC Conserv			Phone 620 225 8888											



## ECHOMETER COMPANY PHONE-940-767-4334

WELL BERR 3-22	JOINTS TO LIQUID 85	08/11/2011 13 QUIET WELL	1: 40: 36	GENERATE	UC
CASING PRESSURE 200 1	DISTANCE TO LIQUID 2447,5	UPPER COLLARS A		PULSE	
ΔP	PBHP	P-P 0,045 mV	•		
ΔΤ	SBHP				
PRODUCTION RATE9	PROD RATE EFF, %				
	MAX PRODUCTION	LIQUID LEVEL A	1: 3.9	12. 1	
		P-P 1,30 mV	<i>}</i>	VOLTS	

