



BASIC
ENERGY SERVICES
PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61
P.O. Box 8613
Pratt, Kansas 67124
Phone 620-672-1201

FIELD SERVICE TICKET
1718 04468 A

DATE _____ TICKET NO. _____

DATE OF JOB <u>10-13-11</u> DISTRICT <u>KANSAS</u>		NEW WELL <input checked="" type="checkbox"/> OLD WELL <input type="checkbox"/> PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/> CUSTOMER ORDER NO.:							
CUSTOMER <u>FG Holl Co. LLC</u>		LEASE <u>NEELAND Trust #1-21</u> WELL NO.:							
ADDRESS		COUNTY <u>STAFFORD 21-22-19</u> STATE <u>KANSAS</u>							
CITY STATE		SERVICE CREW <u>Allen, TJ Gibson, JR. Nuntel</u>							
AUTHORIZED BY		JOB TYPE: <u>8 5/8 Surface CWL</u>							
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	AM/PM	TIME
<u>28443 P4</u>	<u>1</u>						<u>10-12-11</u>	<u>AM</u>	<u>1030</u>
<u>33708-20920</u>	<u>1</u>					ARRIVED AT JOB	<u>10-13-11</u>	<u>AM</u>	<u>1200</u>
<u>30864-19808</u>	<u>1</u>					START OPERATION	<u>10-13-11</u>	<u>AM</u>	<u>430</u>
						FINISH OPERATION	<u>10-13-11</u>	<u>AM</u>	<u>530</u>
						RELEASED	<u>10-13-11</u>	<u>AM</u>	<u>630</u>
						MILES FROM STATION TO WELL	<u>45 miles</u>		

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: _____
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
CP101	A-CON Blend Common	SK	200		
CP100	Common	SK	200		
CC102	Cell Flake	lb	100		
CC109	Calcium Chloride	lb	1128		
CC200	Cement Gel	lb	376		
CF106	Top Rubber cement Plug 8 5/8"	EA	1		
CF1753	Centralizer 8 5/8" Blue	EA	3		
CC131	Sugar	lb	50		
E100	Unit mileage charge Pickup	mi	45		
E101	Heavy Equip mileage	mi	90		
E113	Bulk Delivery charge	TM	846		
C201	Depth Charge 501-1000	4-hr	1		
CE240	Blending & mixing service charge	SK	400		
CF304	Plug container utilization chg	Job	1		
S003	Service Supervisor first 8hrs and loc.	EA	1		

SUB TOTAL
DLS

CHEMICAL / ACID DATA:			

SERVICE & EQUIPMENT	%TAX ON \$
MATERIALS	%TAX ON \$

TOTAL

SERVICE REPRESENTATIVE Alan F Wood

THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: Shawn D. King
(WELL OWNER OPERATOR CONTRACTOR OR AGENT)

FIELD SERVICE ORDER NO.

Customer FG HOLL Co. LLC	Lease No.	Date
Lease NEELAND TRUST	Well # 1-21	10-13-11
Field Order # 04468A	Station Pratt KS	Casing 8 5/8"
Type Job 8 5/8" Surface	Formation CNW	Depth 869'
		County STAFFORD
		State KANS.
		Legal Description 21-22-14

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME		
Casing Size "	Tubing Size	Shots/Ft		Acid	RATE	PRESS	ISIP	
8 5/8"			200SKs	A-con Blend	@ 12.6 #		3% CC, 1/4" C.F.	
Depth	Depth	From	To	Pre Pad	Max		5 Min.	
869'			200SKs	Common	2% gel, 3% CC, 1/4" C.F.		10 Min.	
Volume	Volume	From	To	Pad	Min		15 Min.	
34								
Max Press	Max Press	From	To	Frac	Avg			
500 #								
Well Connection	Annulus Vol.	From	To		HHP Used		Annulus Pressure	
P.C.								
Plug Depth	Packer Depth	From	To	Flush	Gas Volume		Total Load	
847'				9 1/4" H 200				

Customer Representative Steve (Tool Pusher)	Station Manager Scotty	Treater Allen
--	---------------------------	------------------

Service Units	28443	TJ	Gibson	JR	Kuntz				
Driver Names	Allen	33708	20920	30364	19808				

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
1200 AM					on loc. Discuss Safety Setup Plan Job
					Rig making shoot TRIP + CIR 30 min
200					Start out of 160'
300					Start 8 5/8" casing 24'
					Cent 825' - 400' - 40'
430					Pipe @ 869' Hook up + CIR w/Rig.
44.5	200 #		76	5	Mix 200SKs A-con Blend @ 12.6 #
	300 #			5	Mix 200SKs common w/ 2% gel, 3% CC, 1/4" C.F. @ 15 #
			48		Finish mix
					Drop Top Rubber Plug 8 5/8"
515				5	Start Disp.
530	500 #		54	2	Plug down
	0 #				Shut in @ well
					Release PSI To Truck
					Wash up + Rack up Equip.
630					Job Complete
					Cement CIR To Pit.
					THANKS Allen, TJ, JR.