



**BASIC**  
ENERGY SERVICES  
PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61  
P.O. Box 8613  
Pratt, Kansas 67124  
Phone 620-672-1201

FIELD SERVICE TICKET  
1718 05805 A

DATE \_\_\_\_\_ TICKET NO. \_\_\_\_\_

DATE OF JOB <u>12-16-12</u> DISTRICT <u>Pratt</u>		NEW WELL <input checked="" type="checkbox"/> OLD WELL <input type="checkbox"/> PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/> CUSTOMER ORDER NO.:							
CUSTOMER <u>F G HOLL CO LLC</u>		LEASE <u>Bell B</u> <u>1-7</u> WELL NO.							
ADDRESS		COUNTY <u>Barber</u> STATE <u>KS</u>							
CITY STATE		SERVICE CREW <u>Melson Pype Sullivan</u>							
AUTHORIZED BY		JOB TYPE: <u>CNW 4 1/2 LS</u>							
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	AM	TIME
<u>33705 20920</u>	<u>40 m</u>						<u>2/16/12</u>		<u>4:15</u>
<u>19960 19918</u>	<u>40 m</u>					ARRIVED AT JOB	<u>2/16/12</u>	AM	<u>6:45</u>
<u>37900</u>						START OPERATION	<u>2-16-12</u>	AM	<u>2:10</u>
						FINISH OPERATION	<u>2/16/12</u>	AM	<u>2:45</u>
						RELEASED	<u>2-16-12</u>	AM	<u>3:30</u>
						MILES FROM STATION TO WELL			<u>20</u>

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: [Signature]  
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
CP 105735	AA2 Cement	SK	135		
CP 103	60/40 Poz	SK	75		
CL 102	Cello Flake	lb	34		
CL 105	Defoamer	lb	32		
CL 111	SALT	lb	605		
CL 115	Gas Blok	lb	127		
CL 129	FLA-322	lb	127		
CL 201	GILSONITE	lb	1725		
CF 606	Latch Down Plug	eg	1		
CF 1250	Auto Fill Shoe	eg	1		
CF 1650	Turbolizer	eg	8		
CF 1900	4 1/2 Basket	eg	1		
CF 2002	Scratchers	eg	30		
CL 154	Super Flush	gal	500		
E 100	Pickup Mileage	mi	20		
E 101	Heavy Mileage	mi	40		
F 113	Bulk Delivery	TM	192		
CE 205	Depth Charge	4hr	1		
CE 240	Mixing Charge	SK	210		

SUB 1

CHEMICAL / ACID DATA:


SERVICE & EQUIPMENT %TAX ON \$  
MATERIALS %TAX ON \$

[Signature]

SERVICE REPRESENTATIVE <u>[Signature]</u>	THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: <u>[Signature]</u> (WELL OWNER OPERATOR CONTRACTOR OR AGENT)
---	---

FIELD SERVICE ORDER NO.



Customer <i>J. P. Hollen</i>	Lease No.	Date
Lease <i>BEHL-B-1-7</i>	Well # <i>1-7</i>	<i>02-16-12</i>
Field Order # <i>5805</i>	Station <i>PRATT KS</i>	Casing <i>4 1/2</i>
		Depth <i>4901</i>
		County <i>BARBER</i>
		State <i>KS</i>
Type Job <i>CNW 4 1/2 Lowstay</i>	Formation	Legal Description <i>7-30-13</i>

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME		
Casing Size <i>4 1/2</i>	Tubing Size	Shots/Ft		Acid	RATE	PRESS	ISIP	
Depth <i>4901</i>	Depth	From	To	Pre Pad	Max		5 Min.	
Volume <i>77</i>	Volume	From	To	Pad	Min		10 Min.	
Max Press <i>1800</i>	Max Press	From	To	Frac	Avg		15 Min.	
Well Connection <i>PC</i>	Annulus Vol.	From	To		HHP Used		Annulus Pressure	
Plug Depth <i>4839'</i>	Packer Depth	From	To	Flush	Gas Volume		Total Load	

Customer Representative	Station Manager <i>DAVE SCOTT</i>	Treater <i>Robert [Signature]</i>
Service Units <i>37900 33705 20920 1960 1974</i>		
Driver Names <i>Gallo, Wilson, Phyllis</i>		

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
<i>6:45</i>					<i>on loc. safety meeting</i>
					<i>Run 5.75 4 1/2 # 10.5 csg.</i>
<i>12:00</i>					<i>CASING ON BOTTOM</i>
<i>12:10</i>					<i>Hook Reg Circ.</i>
<i>2:10</i>	<i>200</i>		<i>12</i>	<i>3</i>	<i>St Super Seal</i>
			<i>5</i>		<i>SPACER 4 3/4</i>
			<i>6</i>	<i>5</i>	<i>Mix Scavenger cont 25 sk 13.6 ppq.</i>
			<i>34</i>		<i>Mix AA-E cont 135 sk 15.5 ppq.</i>
					<i>cont mix 2.0 with Pump-Liner</i>
					<i>Release Plug</i>
				<i>6</i>	<i>St Dump</i>
	<i>350</i>				<i>Lift Ps.</i>
	<i>600</i>			<i>3.5</i>	<i>Slow Rate</i>
<i>2:45</i>	<i>1800</i>		<i>77</i>		<i>plug down</i>
			<i>7</i>	<i>2</i>	<i>plug R.H w/ 30 sk</i>
			<i>6</i>		<i>plug M.H w/ 20 sk</i>
					<i>JOB COMPLETE</i>
					<i>Thank you</i>