KANSAS CORPORATION COMMISSION 1086842

Form CP-111 March 2009 Form must be Typed Form must be signed All blanks must be complete

TEMPORARY ABANDONMENT WELL APPLICATION

| OPERATOR: License# | | | | API No. 15- | | | | |
|-----------------------------|---------------------|--------------------|-------|-------------------|-----------------------------|----------------------------|---------------|------------|
| Name: | | | | Spot Descr | iption: | | | |
| Address 1: | | | | | Sec | Twp S. R. | | e 🗌 w |
| Address 2: | | | | | | feet from N / | | of Section |
| City: | State: | Zip: + | | | | feet from L E / | | |
| Contact Person: | | | | County: | (e.g. xx.xx) | , Long: | (e.gxxx.xxxxx |) |
| Phone:() | | | | Lease Nam | e: | Well # | : | |
| Contact Person Email: | | | | Elevation:_ | | | G | L 🗌 KB |
| Field Contact Person: | | | | | | Gas OG WSW C | | |
| Field Contact Person Phon | e:() | | | | ermit #: prage Permit #: | ENHR Permit | #: | |
| | | | | | U U | Date Shut-In: | | |
| | Conductor | Surface | Pro | oduction | Intermediate | Liner | Tubing | 9 |
| Size | | | | | | | | |
| Setting Depth | | | | | | | | |
| Amount of Cement | | | | | | | | |
| Top of Cement | | | | | | | | |
| Bottom of Cement | | | | | | | | |
| Casing Fluid Level: | н | ow Determined? | | | | Date: | | |
| Casing Squeeze(s): | b) to w / | sacks of ce | ment, | to | (bottom) W / | sacks of cement. Dat | e: | |
| Do you have a valid Oil & G | Gas Lease? 🗌 Yes 🗌 | No | | | | | | |
| Depth and Type: 🗌 Junk | in Hole at | ☐ Tools in Hole at | h) Ca | sing Leaks: | Yes No Depth | of casing leak(s): | | |
| Type Completion: ALT | T.I ALT. II Depth o | f: DV Tool: | w/ | sacks | s of cement Port C | ollar: w / | sack (| of cement |
| Packer Type: | | | | | | | | |
| Total Depth: | Plug Bac | k Depth: | | Plug Back Meth | od: | | | |
| Geological Data: | | | | | | | | |
| Formation Name | Formation | Top Formation Base | | | Completion | Information | | |
| 1 | At: | to Feet | Perfo | ration Interval | toFe | et or Open Hole Interval | to | Feet |
| 2 | At: | to Feet | Perfo | ration Interval - | to Fe | et or Open Hole Interval _ | to | Feet |

Submitted Electronically

| Do NOT Write in This Space - KCC USE ONLY | Date Tested: | Results: | Date Plugged: | Date Repaired: | Date Put Back in Service: |
|--|--------------|-----------|---------------|----------------|---------------------------|
| Review Completed by: | | Comments: | | TA | Approved: Yes Denied |

Mail to the Appropriate KCC Conservation Office:

| from the line and rate in and find and we have been | KCC District Office #1 - 210 E. Frontview, Suite A, Dodge City, KS 67801 | Phone 620.225.8888 |
|--|--|--------------------|
| | KCC District Office #2 - 3450 N. Rock Road, Building 600, Suite 601, Wichita, KS 67226 | Phone 316.630.4000 |
| | KCC District Office #3 - 1500 SW Seventh Steet, Chanute, KS 66720 | Phone 620.432.2300 |
| | KCC District Office #4 - 2301 E. 13th Street, Hays, KS 67601-2651 | Phone 785.625.0550 |
| Rent Stress June Werk Stat January New State Street Street Street Street | Underground Porosity Gas Storage (UPGS) 8200 E. 34th Street Circle N., Suite 1003, Wichita, KS 67226 | Phone 316.734.4933 |

McKinley 16-I19-30-33 API #15-081-21680-0001 N2 S2 NE SE 19-30S-33W Attachment for Form CP-111

| Formation Name (perfs) | Perforati Top | Perforation Interval Top Bottom |
|------------------------|------------------|------------------------------------|
| St. Louis | 5540 | 5544 |
| Atoka | 5136 | 5138 |
| Atoka | 5124 | 5132 |
| Cherokee | 5018 | 5026 |
| KC | 4648 | 4687 |
| KC A | 4588 | 4595 |
| Lansing G | 4408 | 4420 |
| Lansing | 4190 | 4196 |
| Lansing A | 4143 | 4146 |
| | | |
| Squeeze Perfs | | |
| | 5270 | 5271 |
| | 4686 | 4687 |
| | 4637 | 4638 |
| | 4569 | 4570 |