

Customer <i>Shelby Resources LLC</i>		Lease No.		Date <i>6-30-12</i>	
Lease <i>Towell</i>		Well # <i>#1-34</i>			
Field Order # <i>05934A</i>	Station <i>PRATH KS</i>	Casing	Depth	County <i>Lawrence</i>	State <i>KS</i>
Type Job <i>PTA</i>	Formation <i>cnw</i>	Depth <i>104700'</i>		Legal Description <i>39-21-19</i>	

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME		
Casing Size	Tubing Size	Shots/Ft		Acid	RATE	PRESS	ISIP	
Depth	Depth	From	To	Pre Pad	Max		5 Min.	
Volume	Volume	From	To	Pad	Min		10 Min.	
Max Press	Max Press	From	To	Frac	Avg		15 Min.	
Well Connection	Annulus Vol.	From	To		HHP Used		Annulus Pressure	
Plug Depth	Packer Depth	From	To	Flush	Gas Volume		Total Load	

Customer Representative <i>Larry T.P.</i>	Station Manager <i>Scotty</i>	Treater <i>Allen</i>
--	----------------------------------	-------------------------

Service Units	<i>28443</i>	<i>27463</i>	<i>19826</i>	<i>19918</i>					
Driver Names	<i>Allen</i>	<i>Joe Melson</i>	<i>Steve</i>	<i>Young</i>					

Time	Casing Pressure	Tubing Pressure	Bbbs. Pumped	Rate	Service Log
<i>2:30 pm</i>					<i>on Loc. Discuss Safety Setup Plan Job</i>
					<i>Laying Down Drill Collars</i>
<i>4:30</i>					<i>start in Hole w/ Plugging Stands</i>
<i>7:30</i>				[1st]	<i>D.P. @ 4550 50 SKS 60/40 Poz 4% gel. 13.8</i>
			<i>10</i>	<i>5</i>	<i>Pump 10-BBL H₂O</i>
			<i>12.7</i>	<i>5</i>	<i>Mix + Pump 50SKS cmt</i>
			<i>4</i>	<i>3</i>	<i>Pump 4-BBL H₂O</i>
			<i>59</i>		<i>Disp w/ 59 BBLs MUD.</i>
<i>8:00</i>					<i>Pull Drill pipe</i>
<i>9:30</i>				[2nd]	<i>D.P. @ 1240' 50 SKS 60/40 Poz 4% gel. 13.8</i>
			<i>15</i>	<i>5</i>	<i>Pump 15 BBL H₂O</i>
			<i>12.7</i>	<i>5</i>	<i>Mix + Pump 50SKS cmt</i>
			<i>5</i>	<i>4</i>	<i>Pump 5-BBL H₂O</i>
<i>9:45</i>					<i>Pull Drill Pipe</i>
<i>10:45</i>				[3rd]	<i>D.P. 600' 30-SKS 60/40 Poz 4% gel 13.8</i>
			<i>5</i>	<i>4</i>	<i>Pump 5-BBL H₂O</i>
			<i>7 1/2</i>	<i>5</i>	<i>Mix + Pump 30 SKS 60/40 Poz 4% gel 13.8</i>
<i>10:55</i>			<i>3</i>	<i>4</i>	<i>Pump - 3-BBL H₂O (Pull D.P.)</i>
<i>11:30</i>			<i>5</i>	[4th]	<i>60' To surface 20-SKS</i>
			<i>7 1/2</i>		<i>Rat Hole 30SKS (Pull Mouse Hole)</i>
<i>12:30</i>			<i>5</i>		<i>mouse Hole 20SKS</i>
<i>1:00</i>					<i>washup + Rackup Equip.</i>

Thanks Joe Allen Steve