

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

1130731

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

OPERATOR: License #:			API N	o. 15		
Name:				Spot Description:		
Address 1:				Sec	Twp S. R East West	
Address 2:				Feet from	North / South Line of Section	
City:	State:			Feet from	n East / West Line of Section	
Contact Person:				Footages Calculated from Nearest Outside Section Corner:		
Phone: ()				☐ NE ☐ NW ☐ SE ☐ SW		
Type of Well: (Check one)		OG D&A Cathoo	dic Count	y:		
Water Supply Well Other: SWD Permit #:				Lease Name: Well #:		
ENHR Permit #: Gas Storage Permit #:				Date Well Completed:		
Is ACO-1 filed? Yes No If not, is well log attached? Yes No				The plugging proposal was approved on: (Date)		
Producing Formation(s): List	·			by: (KCC District Agent's Name)		
Depth to	•	ttom: T.D	Pluggi	Plugging Commenced:		
Depth to	o Top: Bo	ttom: T.D		Plugging Completed:		
Depth to	o Top: Bo	ttom: T.D				
01 1 11 1111 1						
Show depth and thickness of		mations.				
Oil, Gas or Wate				Casing Record (Surface, Conductor & Production)		
Formation	Content	Casing	Size	Setting Depth	Pulled Out	
	•	of same depth placed from (bo	•		nods used in introducing it into the hole. If	
Plugging Contractor License #: N			_ Name:			
Address 1:			_ Address 2:			
City:			State:			
Phone: ()						
Name of Party Responsible for	or Plugging Fees:					
State of	County	,	, SS.			
(Print Name)				Employee of Operator of	or Operator on above-described well,	

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and

Form	CP4 - Well Plugging Record			
Operator	LR Energy, Inc.			
Well Name	LINN 16-16			
Doc ID	1136731			

Producing Formations

Formation	Тор	Bottom	Total Depth
Riverton	1136	1138	
Rowe	1081	1082	
Mineral	816	818	
Croweburg	782	784	
Ironpost	755	756	
Mulky	730	735	
Summit	702	706	