

QUALITY OILWELL CEMENTING, INC.

Federal Tax I.D.# 20-2886107

Phone 785-483-2025
Cell 785-324-1041

Home Office P.O. Box 32 Russell, KS 67665

No. 7039

Date	Sec.	Twp.	Range	County	State	On Location	Finish
1-3-14	10	17	19	Rush	KS		11:30 AM
Location				Libenthal 45 to Ave H 4 1/4 W S 1st			

Lease	Irvin Trust	Well No. #1	Owner
Contractor	Royal #1		To Quality Oilwell Cementing, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.
Type Job	Surface		
Hole Size	12 1/4	T.D. 1059'	Charge To Quest Energy
Csg.	8 5/8	Depth 1059'	Street
Tbg. Size		Depth	City State
Tool		Depth	The above was done to satisfaction and supervision of owner agent or contractor.
Cement Left in Csg.	41.86	Shoe Joint 41.86	Cement Amount Ordered 450 com 3% cc 2% G
Meas Line		Displace 64 3/4 bbl	

EQUIPMENT

Pumptrk	5	No.	Cementer	Common
			Helper	Poz. Mix
Bulktrk	12	No.	Driver	Gel.
			Driver	Calcium
Bulktrk	04	No.	Driver	
			Driver	

JOB SERVICES & REMARKS

Remarks:	Hulls
Rat Hole	Salt
Mouse Hole	Flowseal
Centralizers	Kol-Seal
Baskets	Mud CLR 48
D/V or Port Collar	CFL-117 or CD110 CAF 38

Handling

Mileage

8 5/4 FLOAT EQUIPMENT

Guide Shoe

Centralizer

Baskets

AFU Inserts

Float Shoe

Latch Down

Pumptrk Charge


Mileage

Tax

Discount

Total Charge

X Signature *Wong Buehling*



QUALITY OILWELL CEMENTING, INC.

Federal Tax I.D.# 20-2886107

Phone 785-483-2025
Cell 785-324-1041

Home Office P.O. Box 32 Russell, KS 67665

No. 7048

Date	Sec.	Twp.	Range	County	State	On Location	Finish
1-9-14	10	17	19	Rush	Ks		8:15 PM

Location Lebanon 45 4 W 5 10

Lease <u>J. via Trust</u>	Well No. <u>1-10</u>	Owner
Contractor <u>Royalty #1</u>		To Quality Oilwell Cementing, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.
Type Job <u>Production</u>		Charge To <u>Quality Energy</u>
Hole Size <u>7 7/8</u>	T.D. <u>3938</u>	Street
Csg. <u>5 1/2</u>	Depth <u>3925</u>	City
Tbg. Size	Depth	State
Tool	Depth	The above was done to satisfaction and supervision of owner agent or contractor.
Cement Left in Csg. <u>15 24</u>	Shoe Joint <u>15 24</u>	Cement Amount Ordered <u>150 from 10% 5 1/2 5 1/2</u>
Meas Line	Displace <u>93 1/4 bbl</u>	

EQUIPMENT

Pumptrk	No.	Cementer	
5		Helper	<u>Leone W</u>
Bulktrk	No.	Driver	<u>Clayton</u>
14		Driver	
Bulktrk	No.	Driver	
PU		Driver	<u>13</u>

Common

Poz. Mix
Gel.
Calcium
Hulls
Salt
Flowseal
Kol-Seal
Mud CLR 48 <u>500 bbl</u>
CFL-117 or CD110 CAF 38
Sand
Handling
Mileage


JOB SERVICES & REMARKS

Remarks:
Rat Hole - 300
Mouse Hole 15
Centralizers 1, 3, 5, 7, 9, 11, 59+61
Baskets - 59
D/V or Port Collar 2160 @ 1385

FLOAT EQUIPMENT

Guide Shoe
Centralizer <u>4</u>
Baskets <u>1</u>
AFU Inserts
Float Shoe
Latch Down <u>1</u>

Mixed 500 Cat Mud with
Plugged Rat Mouse
Mixed 105 con down 5 1/2
Dashed 95 1/2 bbl
Plug did not bond



X Signature Jim Doolittle

Pumptrk Charge
Mileage
Tax
Discount
Total Charge