



BASICSM
ENERGY SERVICES
PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61
P.O. Box 8613
Pratt, Kansas 67124
Phone 620-672-1201

FIELD SERVICE TICKET
1718 09326 A

DATE 11-22-13 TICKET NO. _____

DATE OF JOB <u>11-22-13</u> DISTRICT <u>Pratt</u>	NEW WELL <input checked="" type="checkbox"/> OLD WELL <input checked="" type="checkbox"/> PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/> CUSTOMER ORDER NO.:
CUSTOMER <u>Griffin Management</u>	LEASE <u>Carr Ouhoo</u> WELL NO. <u>1</u>
ADDRESS	COUNTY <u>Barber</u> STATE <u>ks</u>
CITY STATE	SERVICE CREW <u>Delgado, Anthony, Pearson, Hanson</u>
AUTHORIZED BY	JOB TYPE: <u>5/8 L.C. CCSFW</u>

EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	AM	PM	TIME
274							<u>11-22-13</u>			<u>7:00</u>
<u>27463</u>	<u>1</u>									<u>9:00</u>
<u>19955-19960</u>	<u>1</u>									<u>11:30</u>
<u>28443</u>	<u>1</u>									<u>7:30</u>
<u>33708-20920</u>	<u>1</u>	<u>Griffin Management</u>								<u>1:30</u>
						MILES FROM STATION TO WELL				<u>35</u>

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: _____
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
CP105	AA2 Cement	54	215		365500
CP105	AA2 Cement	52	50		85000
CC102	Coll Stone	Lb	67		24790
CC111	Salt	Lb	1214		60700
CC112	Friction Reducer	Lb	125		25000
CC115	C-44	Lb	250		128750
CC201	Gilswrite	Lb	1330		89110
CF607	Latch Down Plug + Baffle 5 1/2"	ea	1		40000
CF1257	Auto Fill Float Shoe 5 1/2"	ea	1		36000
CF1657	Turbulizer 5 1/2"	ea	7		77000
CF1901	Basket 5 1/2"	ea	1		29000
C704	KCL	Gal	6		21000
CC151	med Slur	Gal	500		43000
E100	Pickup Mileage	M.	35		14875
E101	Heavy Equipment Mileage	M.	70		49000
E113	Bulk Delivery	Tm	438		70000
CE205	Depth Charge 4000-5000'	ea	1		252000
CE240	Blending & Mixing	5x	265		37100
CE504	Plus container	ea	1		25000
J003	Service Supervisor	ea	1		

SUB TOTAL 17500
KG 924195

CHEMICAL / ACID DATA:			

SERVICE & EQUIPMENT	%TAX ON \$	
MATERIALS	%TAX ON \$	
TOTAL		

SERVICE REPRESENTATIVE Steve Orlando THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: TA/H

FIELD SERVICE ORDER NO. _____ (WELL OWNER OPERATOR CONTRACTOR OR AGENT)

Customer <i>Griffin Management</i>	Lease No.	Date <i>11-22-13</i>
Lease <i>Carr Duvvo</i>	Well # <i>1</i>	
Field Order # <i>9326</i>	Station <i>Pratt</i>	Casing <i>5 1/2</i>
	Depth <i>4812</i>	County <i>Barber</i>
Type Job <i>CCSPW-Longspan</i>	Formation	State <i>KS</i>
		Legal Description <i>14-32-12</i>

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME		
Casing Size <i>5 1/2</i>	Tubing Size	Shots/Ft		AA2 Cement <i>2155 lbs</i>	RATE	PRESS	ISIP	
Depth <i>4812</i>	Depth	From	To	Pre Pad <i>1.36 yield</i>	Max		5 Min.	
Volume	Volume	From	To	Pad	Min		10 Min.	
Max Press	Max Press	From	To	Frac	Avg		15 Min.	
Well Connection	Annulus Vol.	From	To		HHP Used		Annulus Pressure	
Plug Depth	Packer Depth	From	To	Flush	Gas Volume		Total Load	

Customer Representative <i>J.R. Griffin</i>	Station Manager <i>Kevin Goodley</i>	Treater <i>Steve Orlando</i>
Service Units <i>27283 27463 19959 19960 33202 20920</i>		
Driver Names <i>Orlando Anthony Poirson Hanson Whitfield</i>		

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
<i>9:00 AM</i>					<i>On location - Safety Meeting</i>
					<i>Run 4812' 5 1/2 15.5# casing</i>
					<i>Centralizers 2-3-6-7-8</i>
					<i>Casing on Bottom - Break Circ w/ris</i>
<i>11:35</i>	<i>300</i>		<i>20</i>	<i>5</i>	<i>H2O w/ KCL</i>
	<i>300</i>		<i>12</i>	<i>5</i>	<i>Mud flush</i>
	<i>300</i>		<i>3</i>	<i>5</i>	<i>H2O spacer</i>
	<i>300</i>		<i>52</i>	<i>5</i>	<i>Mix 215 sls AA2 @ 15.3#/gal</i>
					<i>Shut Down - Clear pump + line</i>
	<i>0</i>		<i>0</i>	<i>6</i>	<i>Start H2O Displacement w/ 20 KCL</i>
	<i>300</i>		<i>80</i>	<i>5</i>	<i>LIFT pressure</i>
	<i>800</i>		<i>105</i>	<i>5</i>	<i>Slow Rate</i>
<i>12:30</i>	<i>1500</i>		<i>114</i>	<i>4</i>	<i>Plug Down - Hold</i>
					<i>Plug 24'/min w/ 50 sls AA2</i>