

JOB LOG

SWIFT Services, Inc.

DATE 1-28-14 PAGE NO. 1

CUSTOMER Dunning & Nelson WELL NO. 1-30 LEASE Amy JOB TYPE Cement Longstring TICKET NO. 25373

CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		DESCRIPTION OF OPERATION AND MATERIALS
				T	C	TUBING	CASING	
<u>1/28</u>	<u>2300</u>					<u>14" TH</u>	<u>5 1/2"</u>	<u>20-3812'</u>
								<u>DN location w/ float equip</u> <u>Rig clearing over</u>
<u>1/29</u>	<u>0015</u>							<u>Start 5 1/2" casing to 3810'</u> <u>Insert float shoe w/ fill up</u> <u>L.D. Baffle - S.J. 2 1/2" = 3789'</u> <u>Cont - 1-3-5-7-9-11</u>
								<u>Drop Killup ball</u>
	<u>0145</u>							<u>Rig Tag bottom Log down ft.</u>
	<u>0200</u>							<u>Start circ / Rotate</u> <u>Get Pump Take Ready</u>
			<u>1/5</u>					<u>Plug RT-30 SKS EA-2 unit</u> <u>MLP 20 SKS EA-2 unit</u>
		<u>6</u>	<u>12</u>				<u>300</u>	<u>Pump 500 gal Mud flush</u>
		<u>6</u>	<u>20</u>				<u>300</u>	<u>Pump 20 BBL Kel flush</u>
		<u>4</u>					<u>200</u>	<u>Start 125 SKS EA-2 unit</u>
			<u>30</u>				<u>200</u>	<u>Fin cont</u> <u>Washout Pump & Lines</u> <u>Drop L.D. Plug</u>
		<u>9</u>					<u>300</u>	<u>Start Disp 1</u>
		<u>9</u>	<u>70</u>				<u>400</u>	<u>Caught 1/2 PL press</u>
		<u>2/8</u>	<u>80</u>				<u>600</u>	<u>slow rate</u>
		<u>6</u>	<u>85</u>				<u>700</u>	<u>slow rate</u>
	<u>040</u>						<u>1000</u> <u>1500</u>	<u>Plug Down - Hold Release & hold</u> <u>Job complete</u> <u>Wash up & Pack up</u> <u>Thanks</u> <u>Alon, Jon & Coase</u>