NO

ROAD

Notes;

shown on this t be legally ndowner, for access.

- 1. Set iron rod at location site.
- 2. All flagging Red & Yellow.
- 3. No overhead power available at Sec. 18.
- 4. Kansas One Call System Inc. should be notified before excavation (1-800-344-7233).
- 5. CAUTION; Various pipelines in Sec. 18.
- 6. Section 18 is irregular.
- 7. Contact landowner for best access.
- 8. Original location (2000'FSL 2000'FWL) fell on the slope of a draw, set new location footages per representative.

- 18 -PASTURE Z-BAR *18-13 TRAIL.

NO

Drillsite Location Z-Bar #18-11 2050'FSL 2030'FWL


Ground Elevation = 1668

 $Y = 152463 \quad X = 1887600$

State Plane-NAD 27-Kansas South (Mapping Grade GPS Used)

ROAD

RIVE



May 22, 2013

Approximate section lines were determined using the normal standard of care of oilfield surveyors practicing in the state of Kansas. The section corners, which establish the precise section lines, were not necessarily located, and the exact location of the drillste location in the section is not guaranteed. Therefore, the operator securing this service and accepting this plat and all other parties relying thereon agree to hold Central Kansas Diffield Services. Inc. its officers and employees harmless from all losses, costs and expenses and said entities released from any liability from incidental or consequential damages.