Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

## **KANSAS CORPORATION COMMISSION**

**OIL & GAS CONSERVATION DIVISION** 

1200459

March 2009 Type or Print on this Form Form must be Signed All blanks must be Filled

Form CP-4

#### WELL PLUGGING RECORD K.A.R. 82-3-117

OPERATOR: License #:	API No. 15
Name:	Spot Description:
Address 1:	Sec Twp S. R East West
Address 2:	Feet from North / South Line of Section
City: State: Zip: +	Feet from East / West Line of Section
Contact Person:	Footages Calculated from Nearest Outside Section Corner:
Phone: ( )	
Type of Well: (Check one)       Oil Well       Gas Well       OG       D&A       Cathodic         Water Supply Well       Other:       SWD Permit #:       SWD Permit #:       SWD Permit #:         ENHR Permit #:       Gas Storage Permit #:       Gas Storage Permit #:       No         Is ACO-1 filed?       Yes       No       If not, is well log attached?       Yes       No         Producing Formation(s): List All (If needed attach another sheet)       Depth to Top:       Bottom:       T.D.	County: Well #: Uell #: Date Well Completed: (Date) by: (KCC District Agent's Name) Plugging Commenced: Plugging Completed: Plugging

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water	Oil, Gas or Water Records		Casing Record (Surface, Conductor & Production)			
Formation	Content	Casing	Size	Setting Depth	Pulled Out	

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

Plugging Contractor License #:		Name: _			
Address 1:		Address	2:		
City:			State:	_ Zip:	_+
Phone: ( )			-		
Name of Party Responsible for Plugging Fe	es:				
State of	County,		, SS.		
	Print Name)		Employee of Operator or		
he for a forest shall a surround and shall be surround. The still be					

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

### Submitted Electronically

# ALLIED OIL & GAS SERVICES, LLC 052531

Federal Tax I.D.# 20-5975804

REMIT TO P.O. BOX 31 RUSSELL, KANSAS 67665

SERVICE POINT:

DATE 3-14-14	SEC.	TWP	RANGE W	CALLED OUT	ON LOCATION	JOB START	JOB FINISH BODOM
LEASEBarker	WELL #	2-23	LOCATION VEC	(and a City	1KS	COLINTY Finney	STATE
OLD OR NEW Cit	and the second second second second	0.00		Carbon 117		1-111109	14,0
CONTRACTOR	pered	0 #1	-	OWNER			
	PTA_	(11)		276 675 31 47 975 35 Fritte			
HOLE SIZE 77	estic	T.D. DEP	TH 1780	CEMENT	NDERED 1603	10 1.0	1110110
TUBING SIZE	046	DEP	and a seal and an out a second	AMOUNT OF	KDERED TWOK	n (00)	40 9 109
	1/2	DEP		processing and a second s			
TOOL	1 A	DEF	The second s				
PRES. MAX			имим	COMMON	96sk	@17.90	1718.40
MEAS. LINE			DE JOINT	POZMIX	Gusk	@ 935	598.40
CEMENT LEFT IN	CSG.			GEL	Cosk	0234	2 140.40
PERFS.			-	CHLORIDE		6	and a second a fighter of the second s
DISPLACEMENT				ASC		@	
	EQU	JIPMENT				@	
PUMP TRUCK	CEMENT	ED ( PA	NV Balza			 @	
A DULA AND	HELPER		100	••••••••••		@	
BULK TRUCK	HELFER	Jane				@	
	DRIVER	Kore	10mu R			_ @	
BULK TRUCK		June,	Jary J.	and an and a second		@	
	DRIVER		*		1176	_@	
*************		<b>198</b> 5 1 <b>07 9</b> 10		- HANDLING	160	-@2.46	411.66
	5.9 4.4	3 4 4 TS T. C.		MILEAGE	0.56	Edita	930,80
	N/ N	MARKS:	1			TOTAL	3799.66
	10	Youn	·				
					SERV	ICE	
*	<b>17432 - 1775 - 1775 - 1775 - 1775</b>	**************************************	*****	DEPTH OF J	09		antarta ana ana ang ang ang ang ang ang ang an
				PUMPTRUC		2249	931
				EXTRA FOO	0.000.000.000.000.000	00177	.09
		·····				67.70	365.00
				- MANIFOLD	0.0	@	
				Additiona	Thours 2	@ 440.0	0 890.00
$\wedge$				and the second		0	
CHARGE TO:	here	XCD					
						ጥስኮል	L 3514.84
STREET							and an and the second s
CITY		TATE	ZIP		PLUG & FLOA	TEOHIDME	NT
						@	
To: Allied Oil &	Gas Serv	ices. LLC.				@	
You are hereby re			nenting equipmer			@	
and furnish ceme						@	-
contractor to do v							
done to satisfaction						TOTA	L
contractor. I have				1			
TERMS AND CO				and the second state and a second state of the	(If Any)		
				TOTAL CHA		314.57	2
	1	1 1	7	IVIAL CHA			
PRINTED NAME	K	DM AS	90E	DISCOUNT		IF PA	ID IN 30 DAYS
	/	1.1	-7	R. Ada	5266.4	5	
SIGNATURE	14	The 1	~	INDI H			
	40		~~~~				
	F		× -				
	1 .						



## **CEMENTING LOG**

Data 2/1	Alonte nue	wint think	al#21 Tick	4 M 8 F	FACAS	
Company		Berexco	Rig	2000 Date:	52531	Spacer Type
lease	Arter inter internet internet	lasker		I No	2-23	AmtSks Yieldft*/sk Density 2
County	house the second se	Inney			Contraction of the second	NNO CONTRACTOR OF CONT
		anney	5131	e	KS	
ocation						LEAD: Time hrs. Type 60/40 4% Gel
		0				Excess
lasing Data	Conductor			uecze	Mec	Amt. 150 Sks Yield 1.5 ft*/sk Density 13.5 P
			eduate Pro		Liner	TAIL: Time hrs. Type
ance S	5/8 Typ	e	Weight	24# Collar		Excess
6076805 <mark>1778</mark> 0090880000.8.600						Amt. Sks Yield ft*/sk Density P
						WATER Lead 7.5 Gal/sk Tail Gal/sk Total BB
lasing Depth	ns Top	0	Bottom	17	50	Pump Trucks Used: 549-550
70763 <del>00 - 10</del> 7690 - 200						Bulk Equipment 472-554
Drill Pipe:	BBLS/	UN. FT	LIN.	FT/BBL		
Open Hole:		UN. FT		FT/BBL		Float Equipment: Manufacturer Weather Ford
apacity Fac			0.0637 LIN.		15.7	Shoe: Type Guide Shoe Depth 1742
asing			.0637 LIN.			
Open Holes	BBIS	LIN. FT C	.1458 LIN.	FT/BBL	6.85	
Drill Pipe	BBLS/	Re-Manager and	LIN	FT/BBL	0.05	Centralizers: QuantityB_PlugsTopBottom
Innulus			0.0735 LIN.	-	13.6	Stage Collars Special Equipment Coment Basket
		UN. FT	and the second second second	FT/BBL	12.0	
erforations	From		The second s			Disp: Fluid Type H2O Amt 108.3 bbis Weight 8.33 P
	11.041	• 1		ft Am	9	Mud Type Weight
OMPANY R	EPRESENTATI	VE	1/m	100		CEMENTER Lenny Baeza
				1		
TIME	the plant was been as a second s	IRES PSI	FLUI	D PUMPED I	ATA	
	PRESSU DRILL PIPE		FLUI	D PUMPED I	RATE	
TIME AM/PM	the plant was been as a second s				RATE	REMARKS
	DRILL PIPE		TOTAL	PUMPED PER	RATE	REMARKS
AM/PM	DRILL PIPE		TOTAL	PUMPED PER	RATE	
AM/PM	DRILL PIPE		TOTAL	PUMPED PER	RATE	REMARKS
AM/PM 12:00am	DRILL PIPE		TOTAL	PUMPED PER	RATE	REMARKS
AM/PM 12:00am	DRILL PIPE		TOTAL	PUMPED PER	RATE	REMARKS On location at 12:00am Rigging up to well head
AM/PM 12:00am	DRILL PIPE		TOTAL	PUMPED PER	RATE	REMARKS
AM/PM 12:00am	DRILL PIPE		TOTAL	PUMPED PER	RATE	REMARKS On location at 12:00em Rigging up to well head
AM/PM 12:00am 4:00am	DRILL PIPE CASING		TOTAL FLUID	PUMPED PER	RATE BBLS/MIN	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew
AM/PM 12:00am 4:00am 4:37am	200		TOTAL FLUID	PUMPED PER	RATE BBLS/MIN	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790'
AM/PM 12:00am 4:00am 4:37am 5:00am	200 100		TOTAL FLUID 100 112	PUMPED PER	RATE BBLS/MIN 5 3	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry
AM/PM 12:00am 4:00am 4:37am	200		TOTAL FLUID	PUMPED PER	RATE BBLS/MIN	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790'
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am	200 100		TOTAL FLUID 100 112 134	PUMPED PER	RATE BBLS/MIN	REMARKS
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:00am	DRILL PIPE CASING 200 100 100 120		TOTAL FLUID 100 112 134 144	PUMPED PER	RATE BBLS/MIN 5 3 5	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am	200 100		TOTAL FLUID 100 112 134	PUMPED PER	RATE BBLS/MIN	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:00am 6:03am	DRILL PIPE CASING 200 100 100 120 100		TOTAL FLUID 100 112 134 144 154	PUMPED PER	RATE BBLS/MIN 5 3 5	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:00am 6:03am	DRILL PIPE CASING 200 100 100 120 100 80		TOTAL FLUID 100 112 134 144 154 164	PUMPED PER	RATE BBLS/MIN 5 3 5	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:00am 6:03am	DRILL PIPE CASING 200 100 100 120 100		TOTAL FLUID 100 112 134 144 154	PUMPED PER	RATE BBLS/MIN 5 3 5 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:00am 6:03am 6:03am	DRILL PIPE CASING 200 100 100 120 100 80 80 80		TOTAL FLUID 100 112 134 144 154 164	PUMPED PER	RATE BBLS/MIN 5 3 5 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry 10 bbls of water ahead to get returns and fill hole
AM/PM 12:00am 4:00am 5:00am 5:00am 6:00am 6:03am	DRILL PIPE CASING 200 100 100 120 100 80		TOTAL FLUID 100 112 134 144 154 164	PUMPED PER	RATE BBLS/MIN 5 3 5 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry 10 bbls of water ahead to get returns and fill hole
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:00am 6:03am 6:55am	DRILL PIPE CASING 200 100 100 120 100 80 80 80		TOTAL FLUID 100 112 134 144 154 164 169	PUMPED PER	RATE B8LS/MIN 5 3 5 4 4 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry 10 bbls of water ahead to get returns and fill hole mixing third plug @ 60' total of 5 bbls of slurry Plugging rat hole
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:03am 6:55am 7:00am	DRILL PIPE CASING 200 100 100 120 100 80 80 80 80 70		TOTAL FLUID 100 112 134 144 154 164 169 175.5	PUMPED PER	RATE B8LS/MIN 5 3 5 4 4 4 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry 10 bbls of water ahead to get returns and fill hole mixing third plug @ 60' total of 5 bbls of slurry
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:03am 6:55am 7:00am	DRILL PIPE CASING 200 100 100 120 100 80 80 80 80 70		TOTAL FLUID 100 112 134 144 154 164 169 175.5	PUMPED PER	RATE B8LS/MIN 5 3 5 4 4 4 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry 10 bbls of water ahead to get returns and fill hole mixing third plug @ 60' total of 5 bbls of slurry Plugging rat hole Plugging mouse hole
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:03am 6:55am 7:00am	DRILL PIPE CASING 200 100 100 120 100 80 80 80 70		TOTAL FLUID 100 112 134 144 154 164 169 175.5	PUMPED PER	RATE B8LS/MIN 5 3 5 4 4 4 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry 10 bbls of water ahead to get returns and fill hole mixing third plug @ 60' total of 5 bbls of slurry Plugging rat hole
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:03am 6:55am 7:00am	DRILL PIPE CASING 200 100 100 120 100 80 80 80 70		TOTAL FLUID 100 112 134 144 154 164 169 175.5	PUMPED PER	RATE B8LS/MIN 5 3 5 4 4 4 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry 10 bbls of water ahead to get returns and fill hole mixing third plug @ 60' total of 5 bbls of slurry Plugging rat hole Plugging mouse hole
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:00am 6:03am 7:00am 7:25am	DRILL PIPE CASING 200 100 100 120 100 80 80 80 70		TOTAL FLUID 100 112 134 144 154 164 169 175.5	PUMPED PER	RATE B8LS/MIN 5 3 5 4 4 4 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry 10 bbls of water ahead to get returns and fill hole mixing third plug @ 60' total of 5 bbls of slurry Plugging rat hole Plugging mouse hole
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:00am 6:03am 7:00am 7:25am	DRILL PIPE CASING 200 100 100 120 100 80 80 80 70		TOTAL FLUID 100 112 134 144 154 164 169 175.5	PUMPED PER	RATE B8LS/MIN 5 3 5 4 4 4 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry 10 bbls of water ahead to get returns and fill hole mixing third plug @ 60' total of 5 bbls of slurry Plugging rat hole Plugging mouse hole leaving location @ 9:00em
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:00am 6:03am 7:00am 7:25am	DRILL PIPE CASING 200 100 100 120 100 80 80 80 70		TOTAL FLUID 100 112 134 144 154 164 169 175.5	PUMPED PER	RATE B8LS/MIN 5 3 5 4 4 4 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry 10 bbls of water ahead to get returns and fill hole mixing third plug @ 60' total of 5 bbls of slurry Plugging rat hole Plugging mouse hole
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:00am 6:03am 7:00am 7:25am	DRILL PIPE CASING 200 100 100 120 100 80 80 80 70		TOTAL FLUID 100 112 134 144 154 164 169 175.5	PUMPED PER	RATE B8LS/MIN 5 3 5 4 4 4 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry 10 bbls of water ahead to get returns and fill hole mixing third plug @ 60' total of 5 bbls of slurry Plugging rat hole Plugging mouse hole leaving location @ 9:00am
AM/PM 12:00am 4:00am 4:37am 5:00am 5:05am 6:03am 6:55am 7:00am	DRILL PIPE CASING 200 100 100 120 100 80 80 80 70		TOTAL FLUID 100 112 134 144 154 164 169 175.5	PUMPED PER	RATE B8LS/MIN 5 3 5 4 4 4 4 4	REMARKS On location at 12:00am Rigging up to well head Safety meeting with rigg crew Pumping water ahead to clean hole out plug @ 1790' Mixing first plug of 50 sk total of 12.6 bbls of slurry Displacement of 22 bbls 10 bbls of water ahead to get returns and fill hole mixing second plug @ 850' total of 10 bbls of slurry 10 bbls of water ahead to get returns and fill hole mixing third plug @ 60' total of 5 bbls of slurry Plugging rat hole Plugging mouse hole leaving location @ 9:00em

4

.