

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

Kansas Corporation Commission OIL & GAS CONSERVATION DIVISION

Form CP-4 March 2009 Type or Print on this Form Form must be Signed All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

OPERATOR: License #:			API No. 15						
Name:					Spot Description:				
Address 1:					Sec Twp S. R East West Feet from North / South Line of Section				
Contact Person:				Footages Calculated from Nearest Outside Section Corner: NE NW SE SW					
Phone: ()									
Water Supply Well ENHR Permit #: Is ACO-1 filed? Yes	Other: Gas Si	OG D&A Cathod SWD Permit #: orage Permit #: ell log attached? Yes		County: Well #: Date Well Completed: The plugging proposal was approved on: (Date)					
Producing Formation(s): List /	•			by:(KCC District Agent's Name)					
Depth to	·	om: T.D		Plugging Commenced:					
Depth to	•	om: T.D		I Plugging Completed:					
Depth to	o Top: Bott	om:T.D							
Chaw donth and thickness of	all water oil and gos form	actions							
Show depth and thickness of Oil, Gas or Wate.		Talloris.	Cooina F	Popord (Surf	ace, Conductor & Produ	untion)			
		Casing	Record (Sun		,				
Formation	Content	Casing	Size		Setting Depth	Pulled Out			
		ged, indicating where the muc if same depth placed from (bo		•					
Plugging Contractor License		Name: _							
Address 1:	Address	ess 2:							
City:				State:					
Phone: ()									
Name of Party Responsible for	or Plugging Fees:								
State of	County,			_ , SS.					
	. 3,				unlayon of Onserter	Operator on above-des	oribod !!		
(Print Name)					ipioyee oi Operator or	Operator on above-des	cribea well,		

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and

6138

QUALITY WELL SERVICE, INC.

Federal Tax I.D. # 481187368

Home Office 324 Simpson St., Pratt, KS 67124

Office 620-727-3410 Fax 620-672-3663

Rich's Cell 620-727-3409 Brady's Cell 620-727-6964

	Sec.	Turn	Danas	1	^t	0.4		I			
Date 04-07-/4	400000	Twp. 235	Range ⊃∂ω		County Wands	State	On Location 400Am	Finish 9:30Am			
Lease BVW		/ell No.	1	·	on Kinsley	LS /4E, SN,	, ~ ~ .	1/2 / 5/			
Contractor Duke #6					Owner M_U/I						
Type Job Rotary PTA					To Quality Well Service, Inc.						
Hole Size 7% T.D. 4710				You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.							
Csg. 85/8 set at 342' Depth			Charge Mul								
Tbg. Size Dail Pipe	16.6	Depth	1410		Street						
Tool		Depth			City		State				
Cement Left in Csg.		Shoe Jo	oint		The above wa	s done to satisfaction ar	d supervision of owner	agent or contractor.			
Meas Line		Displac	e		Cement Amo	ount Ordered 185	5x 60:40:	4%, d+/4			
	EQUIPN	MENT	7		Flosen		•				
Pumptrk 8 No. M. I.					Common)	15					
Bulktrk 10 No. Day	2 13				Poz. Mix 🏅	70					
Bulktrk No.					Gel. 6						
Pickup No.	<u>e Felix</u>	4			Calcium						
JOB SE			RKS		Huils						
Rat Hole $\frac{3}{0}$ $\lesssim x = 7$.	586/s				Salt						
Mouse Hole 205x =	4.1 BG	,/5			Flowseal 46.25						
Centralizers					Kol-Seal Color Col						
Baskets					Mud CLR 48						
D/V or Port Collar					CFL-117 or CD110 CAF 38						
					Sand						
Daill Pipe at 1410'-load Hole, Pump 5 B615 Space					Handling 9						
Mix 505x 60:40 coment Dispul 9 B615 Fre					Mileage (O()						
1/					FLOAT EQUIPMENT						
Dail Preat 370 - load Hole Pung 7861s					Guide Shoe						
Fresh H'D Spacen Mix 50sx 60:40, Disp.					Centralizer						
W/ 2/2 water,					Baskets						
/	····	***************************************			AFU Inserts						
60' mix 35 sx (ement, Cement Did					Float Shoe						
					Latch Down						
Plug Ret & Mouseholes w/50sx cement -					LMV 60						
/					*						
	·····		· · · · · · · · · · · · · · · · · · ·		Pumptrk Cha	rge PTA					
	·····				Mileage (. <u>(1 x Z</u>					
							Tax				
			·				Discount				
Signature (Man Calm							Total Charge				