

DST #1 5269 to 5300 Morrow packer failure

DST #2 5132 to 5300 Morrow 10-45-15-60 GTS 3 min. 1868 mcf Recovered 450' mud; FP 886-901;864-659, SIP 1522-1400, HYD 2695-2482 116 degrees F

DST #3 5050 to 5106 Marmaton (straddle) 10-45-30-60 Recovered 75' mud; FP 115-85; 80-83 SIP 114-115, HYD 2507-2474 115 degrees F

DST #4 6369 to 6718 Viola 10-45-30-60 Recovered 5' mud FP 122-95;103-97, SIP 129-96, HYD 3289-3169 132 degrees F