Form CP-111 June 2011 Form must be Typed Form must be signed

All blanks must be complete


TEMPORARY ABANDONMENT WELL APPLICATION

OPERATOR: License#		API No. 15																			
Name:				Spot Description:																	
Address 1:					Sec	Twp	S. R		E W												
Address 2: State: Zip: +					feet from N / S Line of Section feet from E / W Line of Section																
												Contact Person:				GPS Location: Lat:					
Field Contact Person:				Well Type: (check one) Oil Gas OG WSW Other:																	
Field Contact Person Phone	e:()			SWD Permit #: ENHR Permit #:																	
	,			Gas Storage Permit #: Spud Date: Date Shut-In:																	
				Spud Date.		Date Si	iut-iri.														
	Conductor	Surface	Pr	oduction	Intermediat	e Lir	ner	Tubing	j												
Size																					
Setting Depth																					
Amount of Cement																					
Top of Cement																					
Bottom of Cement																					
Depth and Type:	ALT. II Depth Size:	of: DV Tool:(depth)	w / Inch	sack	s of cement F	Port Collar:(depth,															
Total Depth:	Plug Ba	ck Depth:		Plug Back Meth	iod:																
Geological Date:																					
Formation Name	Formation Top Formation Base			Completion Information																	
1	At:	to Feet	Perfo	oration Interval	to	_ Feet or Open Ho	ole Interval	to	Feet												
2	At:	to Feet	Perfo	oration Interval	to	_ Feet or Open Ho	ole Interval	to	Feet												
INDED DENALTY OF DE	O IIIBV I LIEBEBV ATTI	EST TUAT THE INCODMA	TION CO	NTAINED LIEF	DEIN IS TOLIE AN	D CODDECT TO TH	IE DEST OF F	MV KNOWII I	EDGE												
		Submitt	ed Ele	ectronicall	у																
Do NOT Write in This Space - KCC USE ONLY	Date Tested:	Date Tested: Results:			Date Plugged	d: Date Repaired	l: Date Pu	ut Back in Ser	vice:												
Review Completed by:			Comr	ments:																	
TA Approved: Yes	Denied Date:	_																			
		Mail to the App	ropriate	KCC Conserv	vation Office:																

from their trees now make the new facts among many from their trees.	KCC District Office #1 - 210 E. Frontview, Suite A, Dodge City, KS 67801	Phone 620.225.8888
Name	KCC District Office #2 / UPGS - 3450 N. Rock Road, Building 600, Suite 601, Wichita, KS 67226	Phone 316.630.4000
	KCC District Office #3 - 1500 SW Seventh Steet, Chanute, KS 66720	Phone 620.432.2300
See State State See See See See See See See See See S	KCC District Office #4 - 2301 E. 13th Street, Hays, KS 67601-2651	Phone 785.625.0550

ECHOMETER COMPANY PHONE-940-767-4334

WELL BENGSTON 1-13 CASING PRESSURE 0	JOINTS TO LIQUID NO Tebing DISTANCE TO LIQUID 1456	COLLAR P-P mV 0.068 GENERATE A:10.0 PULSE
ΔΡ,	PBHP	UPPER
ΔΤ	SBHP	
PRODUCTION RATE	PROD RATE EFF, %	
21:05:22 UTC 04/08/2014	MAX PRODUCTION	LIQUID P-P mV 2.354 11.8
	enterior residenti sulcita e e della comita di Carante di Carante di Carante di Carante di Carante di Carante d	A: 5.1 VOLTS



Conservation Division District Office No. 1 210 E. Frontview, Suite A Dodge City, KS 67801



Phone: 620-225-8888 Fax: 620-225-8885 http://kcc.ks.gov/

Sam Brownback, Governor

Shari Feist Albrecht, Chair Jay Scott Emler, Commissioner Pat Apple, Commissioner

May 07, 2014

Sarah Rodriguez Chesapeake Operating, Inc. 6100 N WESTERN AVE PO BOX 18496 OKLAHOMA CITY, OK 73118-0496

Re: Temporary Abandonment API 15-075-30095-00-01 BENGTSON 1-13 NE/4 Sec.13-21S-41W Hamilton County, Kansas

Dear Sarah Rodriguez:

"Your temporary abandonment (TA) application for the well listed above has been approved. In accordance with K.A.R. 82-3-111 the TA status of this well will expire 05/07/2015.

- * If you return this well to service or plug it, please notify the District Office.
- * If you sell this well you are required to file a Transfer of Operator form, T-1.
- * If the well will remain temporarily abandoned, you must submit a new TA application, CP-111, before 05/07/2015.

You may contact me at the number above if you have questions.

Very truly yours,

Steve Pfeifer"