



**CONSOLIDATED**  
Oil Well Services, LLC

TICKET NUMBER **46850**

LOCATION **Oakley KS**

FOREMAN **Jerry Y Furry**

PO Box 884, Chanute, KS 66720  
620-431-9210 or 800-467-8676

**FIELD TICKET & TREATMENT REPORT**  
**CEMENT**

DATE	CUSTOMER #	WELL NAME & NUMBER	SECTION	TOWNSHIP	RANGE	COUNTY
4-29	2199	Frazee 1-23	23	235	40w	Hamilton
CUSTOMER			TRUCK #			
MAILING ADDRESS			DRIVER			
CITY			TRUCK #			
STATE			DRIVER			
ZIP CODE						

JOB TYPE **AWP** HOLE SIZE \_\_\_\_\_ HOLE DEPTH \_\_\_\_\_ CASING SIZE & WEIGHT **4 1/2**  
 CASING DEPTH \_\_\_\_\_ DRILL PIPE \_\_\_\_\_ TUBING **2 3/8** OTHER \_\_\_\_\_  
 SLURRY WEIGHT **13.8** SLURRY VOL **1.42** WATER gal/sk **6.9** CEMENT LEFT in CASING \_\_\_\_\_  
 DISPLACEMENT \_\_\_\_\_ DISPLACEMENT PSI \_\_\_\_\_ MIX PSI \_\_\_\_\_ RATE \_\_\_\_\_

REMARKS: *Safety meeting & rig up on well head mix 100 SKS of 60/40 4% gel 1/4 flocculants with 150# cotton seed hulls in the first 18 SKS of slurry and displaced 17 bbl and obtained 500' position perfs @ 2464 run bond log perforated @ 250 run tubing to 900' mix 40 SKS & disp 1/2 bbl pull tubing hook on to casing & mix 75 SKS to top off casing & backside to 30' & topped off using a total of 215 SKS.*

*Thank you Jerry & crew*

**AFE # 803077**

ACCOUNT CODE	QUANTITY or UNITS	DESCRIPTION of SERVICES or PRODUCT	UNIT PRICE	TOTAL
5405A	1	PUMP CHARGE	875 <sup>00</sup>	875 <sup>00</sup>
5406	75	MILEAGE	5 <sup>25</sup>	393 <sup>75</sup>
5407A	9.3	ton mileage delivery	1 <sup>35</sup>	1220 <sup>63</sup>
1131	215 SKS	60/40 102 mix	15 <sup>86</sup>	3409 <sup>90</sup>
1118b	740 #	bentonite gel	27	19980
1107	54 #	flow seal	297	16038
1105	150 #	cotton seed Hulls	58	8700
			Subtotal	6346 <sup>46</sup>
			less 10%	6346 <sup>46</sup>
			Subtotal	5711 <sup>82</sup>

SALES TAX ESTIMATED TOTAL \_\_\_\_\_  
 AUTHORIZATION *Dennis Paul* TITLE \_\_\_\_\_ DATE \_\_\_\_\_

I acknowledge that the payment terms, unless specifically amended in writing on the front of the form or in the customer's account records, at our office, and conditions of service on the back of this form are in effect for services identified on this form.