

Pro-Stake LLC

Oil Field & Construction Site Staking

P.O. Box 2324 Garden City, Kansas 67846 Office/Fax: (620) 276-6159 Cell: (620) 272-1499

burt@pro-stakellc.kscoxmail.com



001619 PLAT NO.

Murfin Drilling Company, Inc.

PERATOR

Rush County, KS

COUNTY

32 16s 19w Sec. Twp. Rng. Littler LLC 'B' #1-32

LEASE NAME

335' FNL - 2305' FEL

LOCATION SPOT

SCALE: 1" = 1000'

DATE STAKED: June 20th, 2014

MEASURED BY: Kent C.

DRAWN BY: Norby S.


AUTHORIZED BY: Shauna G.

This drawing does not constitute a monumented survey or a land survey plat.

This drawing is for construction purposes only.

GR. ELEVATION: 2058.6°

Directions: From the SE side of McCraken, KS at the intersection of Hwy 4 & Elm Ave. – Now go 2 miles North on Hwy 4 – Now go 6 miles East on Ave. G to the SW corner of section 32-16s-19w – Now go 1 mile North on CR 170 Rd. – Now go 0.5 mile East on Ave. F Rd. to ingress stake South into – Now go 335' South through wheat stubble to ingress stake East into – Now approx. 335' East through wheat stubble, into staked location. **Final ingress must be verified with land owner or Operator.**





Rush County, KS

COUNTY

Pro-Stake LLC

Oil Field & Construction Site Staking

P.O. Box 2324 Garden City, Kansas 67846 Office/Fax: (620) 276-6159 Cell: (620) 272-1499 burt@pro-stakellc.kscoxmail.com



001619

Murfin Drilling Company, Inc.

OPERATOR

32 16s 19w
Sec. Twp. Rng.

Littler LLC 'B' #1-32

LEASE NAME

335' FNL - 2305' FEL LOCATION SPOT

SCALE: 1" = 1000'

DATE STAKED: June 20th, 2014

MEASURED BY: Kent C.

DRAWN BY: Norby S.

AUTHORIZED BY: Shauna G.

This drawing does not constitute a monumented survey or a land survey plat.

This drawing is for construction purposes only.

GR. ELEVATION: $\frac{2058.6}{}$

Directions: From the SE side of McCraken, KS at the intersection of Hwy 4 & Elm Ave. – Now go 2 miles North on Hwy 4 – Now go 6 miles East on Ave. G to the SW corner of section 32-16s-19w – Now go 1 mile North on CR 170 Rd. – Now go 0.5 mile East on Ave. F Rd. to ingress stake South into – Now go 335' South through wheat stubble to ingress stake East into – Now approx. 335' East through wheat stubble, into staked location.

