

QUALITY OILWELL CEMENTING, INC.

Federal Tax I.D.# 20-2886107

Phone 785-483-2025

Home Office P.O. Box 32 Russell, KS 67665

No. 540

Cell 785-324-1041

Date	Sec.	Twp.	Range	County	State	On Location	Finish
8-20-14	35	11	15	Russell	KS		8:30 PM

Location Canyon Rd to Roller Coaster Rd 3W

Lease Euler Ranch N-35	Well No. #2	Owner
Contractor Royal #1		To Quality Oilwell Cementing, Inc.
Type Job Surface		You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.
Hole Size 12 1/4	T.D. 221	Charge To ESP
Csg. 8 5/8	Depth 221	Street
Tbg. Size	Depth	City State
Tool	Depth	The above was done to satisfaction and supervision of owner agent or contractor.
Cement Left in Csg. 20'	Shoe Joint	Cement Amount Ordered 150 con 30 acc 20 1/2 gal
Meas Line	Displace 12 3/4	

EQUIPMENT

Pumptrk 18	No.	Cementer
		Helper Clayton
Bulktrk 1	No.	Driver Ryan
Bulktrk PU	No.	Driver Brett

Common

Poz. Mix

Gel.

Calcium

JOB SERVICES & REMARKS

Remarks:	Salt
Rat Hole	Flowseal
Mouse Hole	Kol-Seal
Centralizers	Mud CLR 48
Baskets	CFL-117 or CD110 CAF 38
D/V or Port Collar	Sand
	Handling
	Mileage

FLOAT EQUIPMENT

Cement	Guide Shoe
	Centralizer
	Baskets
	AFU Inserts
	Float Shoe
	Latch Down

Pumptrk Charge


Mileage

Tax

Discount

Total Charge

X Signature *[Signature]*



QUALITY OILWELL CEMENTING, INC.

Federal Tax I.D.# 20-2886107

Phone 785-483-2025
Cell 785-324-1041

Home Office P.O. Box 32 Russell, KS 67665

No. 333

Date	Sec.	Twp.	Range	County	State	On Location	Finish
8-25-14	3	11	15	Russell	KS	7:30 AM	11:00 AM
Lease <u>Euler Ranch</u>				Well No. <u>#2</u>	Owner <u>N to ISO 2 N E into</u>		
Contractor <u>Boyer</u>				<u>1</u>	To Quality Oilwell Cementing, Inc.		
Type Job <u>Long Stairs</u>				You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.			
Hole Size <u>7 7/8</u>	T.D. <u>3400</u>		Charge To <u>ESP</u>				
Csg. <u>5/8</u>	Depth <u>3397</u>		Street				
Tbg. Size	Depth		City		State		
Tool		Depth		The above was done to satisfaction and supervision of owner agent or contractor.			
Cement Left in Csg. <u>21.54</u>	Shoe Joint <u>21.54</u>		Cement Amount Ordered <u>450 QMDC</u>				
Meas Line <u>14</u>	Displace <u>82.26 BBL</u>		100 Com 10% salt + 24 flow				
EQUIPMENT				Common			
Pumptrk <u>20</u>	No.	Cementer	Poz. Mix				
Bulktrk <u>19</u>	No.	Helper	Gel.				
Bulktrk <u>3</u>	No.	Driver	Calcium				
JOB SERVICES & REMARKS				Hulls			
Remarks:				Salt			
Rat Hole <u>30 SWS</u>				Flowseal			
Mouse Hole <u>15 SWS</u>				Flowseal <u>HCL 20 BBL</u>			
Centralizers <u>13 SWS</u>				Mud CLR 48 <u>500 g</u>			
Baskets				CFL-117 or CD110 CAF 38			
DV or Port Collar				Sand			
<u>Calculated 45 min</u>				Handling			
<u>then mud flush with</u>				Mileage			
<u>20 BBL of HCL behind</u>				<u>SH</u> FLOAT EQUIPMENT			
<u>it plug Port and mouse</u>				Guide Shoe			
<u>note mixed cement</u>				Centralizer <u>turbos 7</u>			
<u>displace with water</u>				Baskets <u>OH</u>			
<u>Lift 900 psi</u>				AFU Inserts			
<u>Land 1600 psi</u>				Float Shoe <u>1</u>			
<u>Cement did</u>				Latch Down <u>1</u>			
<u>circulate</u>				Bubble Plug			
				Rotator			
				Pumptrk Charge			
				Mileage			
				Tax			
				Discount			
				Total Charge			
Signature <u>Wong Boyer</u>							