

QUALITY WELL SERVICE, INC.

6146

Federal Tax I.D. # 481187368

Home Office 324 Simpson St., Pratt, KS 67124

Office 620-727-3410
Fax 620-672-3663

Rich's Cell 620-727-3409
Brady's Cell 620-727-6964

Date	05-07-14	Sec.	10	Twp.	28s	Range	23w	County	Ford	State	KS	On Location	8:30 AM	Finish	11:30 AM	
Lease	Droste		Well No.	2-10		Location Ford KS, 1/4 N, 3 W, 1 S, 3/4, 5/8 in to										
Contractor	Duke #1							Owner	Vincent							
Type Job	Surface							To Quality Well Service, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.								
Hole Size	12 1/4		T.D.	248 650												
Csg.	8 5/8 24"		Depth	248 649.		Charge To	Vincent									
Tbg. Size			Depth			Street										
Tool			Depth			City State										
Cement Left in Csg.	42'		Shoe Joint	42.23		The above was done to satisfaction and supervision of owner agent or contractor.										
Meas Line			Displace	38 1/2 Bbls Fresh		Cement Amount Ordered	125sx MDC # 125sx class A									
EQUIPMENT						+ 2% gel + 3% occ 1/4 c.f.										
Pumptrk	8	No.	Mike B			Common	125									
Bulktrk	10	No.	Dave B			Roz Mix	MDC 125									
Bulktrk	9	No.	Dave F			Gel.	11									
Pickup		No.	Darin			Calcium	10									
JOB SERVICES & REMARKS						Hulls										
Rat Hole						Salt										
Mouse Hole						Flowseal	66.25									
Centralizers						Kol-Seal										
Baskets						Mud CLR 48										
D/V or Port Collar	Ran 15 jts 8 5/8 csg					CFL-117 or CD110 CAF 38										
Pipe on B Hm, Break Circ., Pump 3 Bbls						Sand										
Spacer, Mix 125sx MDC, # 49.87 Bbls Slurry						Handling 271										
Mix 125sx A 3#2 cement, = 47.73 Bbls Slurry						Mileage 50										
Stop Pump, Release Plug, Start Disp. w/						FLOAT EQUIPMENT										
Fresh H2O, wash up on Plug, See Steady						Guide Shoe										
increase in PSI @ Bbls Slow Rate,						Centralizer										
Bump Plug, Shut in at 38 1/2 Bbls total						Baskets										
Disp. w/ 450# PSI, Cement Did Circ.						AFU Inserts										
						Float Shoe Secure Supervisor										
						Latch Down LMV 50										
						Baffle Plate 8 5/8										
						8 5/8 wooden Plug.										
						Pumptrk Charge Surface.										
						Mileage 50 x 2										
						Tax										
						Discount										
						Total Charge										
X Signature	Mike Adams															

QUALITY WELL SERVICE, INC.

6149

Federal Tax I.D. # 481187368

Home Office 324 Simpson St., Pratt, KS 67124

Office 620-727-3410
Fax 620-672-3663

Rich's Cell 620-727-3409
Brady's Cell 620-727-6964

Date	05-16-14	Sec.	10	Twp.	28s	Range	23w	County	Ford	State	KS	On Location	1:30AM	Finish	7:15AM
Lease	Droste		Well No.	2-10		Location Ford KS, w to 122 nd , 1s, 3/4w, f into									
Contractor	Duke #1							Owner Vincent							
Type Job	Production							To Quality Well Service, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.							
Hole Size	7 7/8		T.D.	5138											
Csg.	5 1/2		Depth	5137											
Tbg. Size	14"		Charge To	Vincent											
Tool			Street												
Cement Left in Csg.	42'		Depth												
Meas Line			City	State											
			Shoe Joint	42											
			Displace	Bbls 2% KCL											
			Cement Amount Ordered	225sx Pro C + 5# Kol Seal											
EQUIPMENT										10% Salt					
Pumptrk	8	No.	David B		Common										
Bulktrk	5	No.	Mike B		225sx Pro C										
Bulktrk		No.			Poz. Mix										
Pickup		No.	David F		Gel.										
JOB SERVICES & REMARKS										Hulls					
Rat Hole	30sx		8.4 Bbls												
Mouse Hole	20sx		5.6 Bbls												
Centralizers			Kol-Seal 1125#												
Baskets			Mud CLR 48 500 gal												
D/V or Port Collar			CFL-117 or CD110 CAF 38 CC-1 12 Gal												
Pipe on Btm, Break Csg, - Pump Preflush										Sand					
18 Bbls, Plug rat & Mouse holes w/ 50sx										Handling 249					
cement = 14 Bbls, Mix 175sx Pro C										Mileage 50					
Cement = 48.93 Bbls, Stop-Wash Pump										FLOAT EQUIPMENT					
& Lines, Release Plug, Start Disp. w/										Guide Shoe 1-5 1/2					
2% KCL Water, See Steady increase in										Centralizer 6-5 1/2					
PSI @ 84 Bbls, Slow Rate, Slow again										Baskets					
at 115, Bump Plug at 124 1/2 Bbls total										AFU Inserts 1-5 1/2					
Disp. from 800 PSI to 1100 PSI										Float Shoe					
Release PSI, Float Did Hold										Latch Down 1 Top Rubber Plug					
										Supervision					
										LMV 50					
										Pumptrk Charge Long string					
										Mileage 50 x 2					
										Tax					
										Discount					
										Total Charge					
X Signature 															