

QUALITY WELL SERVICE, INC.

6182

Federal Tax I.D. # 481187368

Home Office 324 Simpson St., Pratt, KS 67124

Office 620-727-3410

Fax 620-672-3663

Rich's Cell 620-727-3409

Brady's Cell 620-727-6964

Date 6-26-14	Sec. 29	Twp. 18	Range 28	County Lane	State KS	On Location 10:00 AM	Finish 1:00 PM
Lease Kalo Unit		Well No. 1-29		Location 2E 1S 1/2W of Dighton			
Contractor HD 3				Owner			
Type Job Rotary Plug				To Quality Well Service, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.			
Hole Size		T.D.		Charge To Larson			
Csg.		Depth		To			
Tbg. Size		Depth		Street			
Tool		Depth		City State			
Cement Left in Csg.		Shoe Joint		The above was done to satisfaction and supervision of owner agent or contractor.			
Meas Line		Displace		Cement Amount Ordered 270sx 60/40 4% Gel 1/4 C.F.			
EQUIPMENT							
Pumptrk 8	No.	David		Common	165		
Bulktrk 10	No.	Mike		Poz. Mix	105		
Bulktrk	No.			Gel.	9		
Pickup	No.			Calcium			
JOB SERVICES & REMARKS				Hulls 1			
Rat Hole 30sx				Salt			
Mouse Hole				Flowseal 67.50			
Centralizers				Kol-Seal			
Baskets				Mud CLR 48			
D/V or Port Collar				CFL-117 or CD110 CAF 38			
1st Loaded hole with Mud.				Sand			
				Handling 279			
2nd Pumped 8bbls H²/o mixed 50sx 60/40 4% Gel displaced with 3bbls H²/o 24bbls mud @ 2160'				Mileage 35			
				FLOAT EQUIPMENT			
				Guide Shoe			
				Centralizer			
3rd Pumped 8bbls H²/o mixed 80sx 60/40 4% Gel displaced with 14bbls H²/o @ 1320'				Baskets			
				AFU Inserts			
				Float Shoe			
4th Pumped 5bbls H²/o mixed 40sx 60/40 4% Gel displaced with 6bbls H²/o @ 600'				Latch Down			
				Service Supervisor			
				LMV 35			
5th Pumped 3bbls H²/o mixed 50sx 60/40 4% Gel displaced with 1 bbl H²/o @ 300'				Pumptrk Charge Rotary Plug			
				Mileage 35X2			
				Tax			
				Discount			
6th Pumped 20sx 60/40 4% Gel to surface from 60'				Total Charge			
Signature [Signature]							