

PENNY'S

Chrisjan #5





www.pennysconcrete.com An Equal Opportunity Employer CONCRETE, INC. 23400 W. 82ND STREET

SHAWNEE MISSION, KANSAS 66227-2705 DISPATCH: (913) 441-4197 OFFICE (913) 441-8781 American Concrete Institute



KANSAS
DEPARTMENT OF TRANSPORTATION
Certifications

(800) 322-9710 (800) 524-6474 PT,ANT 8045491 COD8 0145 Steve Wilson 10/31/2014 08 ADDITIONAL DIRECTIONS AND/OR SPECIAL INSTRUCTIONS CUSTOMER NAME ** PAID BY CREDIT CARD **69 HWYSOUTH - 68 COD - BAUER OIL HWY WEST - 169 HWY SOUTH - 7 HWY NORTH -JOB ADDRESS TAKE THE FRONTAGE RD/371ST ST/SUNSHINE RD SUNSHINE RD & 169 HWY - OSAWATOM IE, KS WEST TO THE JOB KOTE: ALL DRIVERS MUST WEAR A HARD HAT, SAFRTY GLASSES, 0 STREL TOE BOOTS, AND SAFETY VEST ON EVERY JOE! PREVIOUS TRUCK STUMP APPLICATION PROJECT CODE ORDER 9 EXTEW 53 CREDITCARD AMOUNT DELIVERED UNIT PRICE ORDERED DESCRIPTION QTY. 3.00 \$338.001,014.00 GALLONS 3.00 SLURRY20-20 SACK SLURRY -3.00 CYDS \$54.00 \$18.00 3.00 3.00 SHORT LOAD CHARGE 3.00 ea \$6.60 \$6.60 FUEL SURCHARGE - PER LOAD 0.00 1.00 FUELINV 03

				SUSTOTAL	\$1,074.60
LEAVE PLANT	ARRIVE JOB	START UNLOAD	FINISH UNLOAD	XAT	\$92.95
LEAVE JOB	ARRIVE PLANT	TEST CYLINDERS TAKEN			1 - 7 - 7 - 7
		E ACCEPTS RECEIPT OF THIS LOAD OF galydsgalydsgal		CTED GRAND TOWAL	\$1,167.55

CAUTION! Cement powder or freshly mixed concrete, grout or mortar may cause skin injury. Avoid contact with skin and wash exposed areas promptly with water. If any cement powder or mixture gets into the eyes, rinse immediately and repeatedly with water, and get prompt medical attention. Keep children away from all freshly mixed cement products. MSDS on reverse side.

ANY WATER ADDED TO MIX ON THE JOB WILL BE AT THE PURCHASER'S RISK

DELIVERY AGREEMENT: This purchase agreement is for delivery to the curb line. In the event Purchaser requests delivery beyond the curb line, the Purchaser hereby assumes liability for damages to sidewalks, driveways all other property, and personal injury. Purchaser hereby agrees to indemnify and hold the Seller harmless against all liability, loss or expense incurred as the result of such delivery. If ground conditions beyond the curb line are inadequate for heavy truck travel, and as a result of this condition the truck requires towing, towing will be at the customer's expense.

PRODUCT PERFORMANCE: All concrete sold on a basis of compressive strength, air-entrainment, slump, temperature, density and or yield must be sampled at the mixer truck discharge in accordance to ASTM C172 and tested according to the applicable ASTM testing standards. Compressive strength: ASTM C31 & ASTM C39; air content: ASTM C231 or ASTM C173; Slump: ASTM C173; Slump:

ADDITIONAL INFORMATION: Ambient conditions may produce rapid evaporation of moisture from the concrete surface. As a result, plastic shrinkage cracking may occur. Precautions should be taken. Drying shrinkage is an inherent, unavoidable property of concrete and precautions should be taken to minimize random cracking. Control joints must be properly constructed with reference to location, spacing, depth and timing. Materials hereby sold become property of purchaser at point of origin. The purchaser shall in no event accept deliveries of materials not in accord with the agreement of the parties, but such materials shall be refused by the purchaser and returned to the seller with a written statement of the reason for the refusal thereof. No cancellation accepted after concrete has been batched.

MSDS and Lien Law information on reverse side.

RECEIVED IN GOOD CONDITION BY			
		X	
		CUSTOMER SIGNATURE	
PRINTED NAME	TITLE	NO WARRANTY IMPLIED OR EXPRESSED ON PRODUCT	