Following is a log top comparison of your well to the Prospect #2 Deyle and the Advantage Spears oil well logs. These wells are located south and north (respectively) of the subject well:

Note that your hand-held GPS unit indicated the Vernice 15-5 GL had been elevated 7 ft compared to the RLS surveyed GL during the location construction process. Therefore, I corrected log tops below to the new **KB elevation of 3064**'. However, the Pioneer O-H logs do not reflect the correction (which was discovered after logging):

LOG TOP COMPARISON:

<u>Formation</u>	Vernice 15-5 O-H log tops	comp to Deyle 2 O-H log tops		comp to Spears O-H log tops	
			(00)		(. 50)
Anhydrite	2992(+72)	-16	(+88)	-1	(+73)
Foraker Ls.	3572(-508)	-12	(-496)	+3	(-511)
Topeka Ls.	3794(-730)	-11	(-719)	+17	(-747)
Oread Ls.	3907(-843)	-16	(-827)	+2	(-845)
LKC "A"	4000(-936)	-12	(-924)	+7	(-943)
LKC "E"	4200(-1136)**	-13	(-1123)	+3	(-1139)
Base KC	4288(-1224)**	-11	(-1213)	+9	(-1233)
RTD 4300'					

If you have any questions, please call me at 785-819-2460. Thank you for this opportunity to serve you!

Sincerely,

Robert T. Hopkins, L.G., C. P. G.

Ruht T. Hohn.

attachments

