

MARK MORRISON
1651 50th Road
Yates Center, KS 66783

WORK ORDER

MEARS M

<u>DATE</u>	<u>WELL</u>	<u>DESCRIPTION</u>
11/21/2014	MO-14	mixed 8 sacks of cement to cement surface
11/26/2014	MO-14	established circulation; circulate 125 sacks of cement to surface pumped plug and set float shoe