

MARK MORRISON
1651 50th Road
Yates Center, KS 66783

WORK ORDER
MEARS B

<u>DATE</u>	<u>WELL</u>	<u>DESCRIPTION</u>
12/12/2014	B-05	mixed 8 sacks of cement to cement surface
12/17/2014	B-05	established circulation; circulate 105 sacks of cement to surface pumped plug and set float shoe