



PAGE	CUST NO	YARD #	INVOICE DATE
1 of 1	1007589	1718	01/16/2015
INVOICE NUMBER			J
91703144			

Pratt (620) 672-1201
 B HERMAN L LOEB LLC
 I PO Box: 838
 L LAWRENCEVILLE
 L IL US 62439
 T
 O ATTN: ACCOUNTS PAYABLE

J LEASE NAME Clark 8
 O LOCATION
 B COUNTY Sumner A 786
 S STATE KS
 I JOB DESCRIPTION Cement-New Well Casing/Pi
 E JOB CONTACT 9438

JOB #	EQUIPMENT #	PURCHASE ORDER NO.	TERMS	DUE DATE	
40806530	20920		Net - 30 days	02/15/2015	
		QTY	U of M	UNIT PRICE	INVOICE AMOUNT
For Service Dates: 01/15/2015 to 01/15/2015					
0040806530					
171812153A Cement-New Well Casing/Pi 01/15/2015 Cement 5 1/2" Longstring					
50/50 POZ		300.00	EA	6.82	2,046.00 T
Celloflake		75.00	EA	2.29	172.05 T
Gypsum		1,260.00	EA	0.47	585.90 T
FLA-322		126.00	EA	4.65	585.90 T
Mud Flush		1,000.00	EA	0.93	930.00 T
Gilsonite		1,800.00	EA	0.42	747.72 T
KCL Potassium Chloride		680.00	EA	0.93	632.40 T
Claymax KCL Substitute		4.00	EA	21.70	86.80 T
"Latch Down Plug & Baffle, 5 1/2"" (Blu		1.00	EA	248.00	248.00
"Auto Fill Float Shoe 5 1/2"" (Blue)"		1.00	EA	223.20	223.20
"Turbolizer, 5 1/2"" (Blue)"		12.00	EA	68.20	818.40
"5 1/2"" Basket (Blue)"		2.00	EA	179.80	359.60
"Unit Mileage Chg (PU, cars one way)"		80.00	MI	2.79	223.20
Heavy Equipment Mileage		160.00	MI	4.65	744.00
"Proppant & Bulk Del. Chgs., per ton mil		1,008.00	EA	1.55	1,562.40
Depth Charge; 3001-4000'		1.00	EA	1,339.20	1,339.20
Blending & Mixing Service Charge		300.00	BAG	0.87	260.40
Casing Swivel Rental		1.00	EA	124.00	124.00
Plug Container Util. Chg.		1.00	EA	155.00	155.00
"Service Supervisor, first 8 hrs on loc.		1.00	EA	108.50	108.50

PAID

JAN 20 2015

SCANNED

PLEASE REMIT TO:	SEND OTHER CORRESPONDENCE TO:	56326	SUB TOTAL	11,952.67
BASIC ENERGY SERVICES, LP	BASIC ENERGY SERVICES, LP		TAX	384.82
PO BOX 841903	801 CHERRY ST, STE 2100		INVOICE TOTAL	12,337.49
DALLAS, TX 75284-1903	FORT WORTH, TX 76102			



BASICSM
ENERGY SERVICES
 PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61
 P.O. Box 8613
 Pratt, Kansas 67124
 Phone 620-672-1201

2 313

FIELD SERVICE TICKET

~~1718-12154~~ A

Continue

DATE TICKET NO 1718 12153A

DATE OF JOB: 01-15-15	DISTRICT: Pratt	NEW WELL <input checked="" type="checkbox"/>	OLD WELL <input type="checkbox"/>	PROD <input type="checkbox"/>	INJ <input type="checkbox"/>	WDW <input type="checkbox"/>	CUSTOMER ORDER NO.:			
CUSTOMER: Herman L. Loeb L.L.C.		LEASE: Clark			WELL NO. 8					
ADDRESS:		COUNTY: Sumner		STATE: KS						
CITY:		SERVICE CREW:								
AUTHORIZED BY:		JOB TYPE: (WVW - 5 1/2 LONGSTRING)								
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	AM	PM	TIME
						ARRIVED AT JOB				AM
						START OPERATION				AM
						FINISH OPERATION				PM
						RELEASED				AM
						MILES FROM STATION TO WELL				

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: [Signature]
 (WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT	
E 100	Pickup mileage	Mi	80		360 -	
E 101	Heavy Equipment Mileage	Mi	160		1200 -	
E 113	Bulk Delivery	T/M	1008		2520 -	
CE 204	Depth Charge	4hr	1		2160 -	
CE 240	Mixing Charge	SK	300		420 -	
CE 504	Plug container	job	1		250 -	
CE 501	Casing Swivel Rental	Ea	1		200 -	
S003	Service Supervisor	Ea	1		175 -	
					SUB TOTAL	19278 50
CHEMICAL / ACID DATA:						
SERVICE & EQUIPMENT					%TAX ON \$	
MATERIALS					%TAX ON \$	
					TOTAL	KG 11,952 67

Discounted

SERVICE REPRESENTATIVE: [Signature]
 FIELD SERVICE ORDER NO.:

THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: [Signature]
 (WELL OWNER OPERATOR CONTRACTOR OR AGENT)

Customer <i>Herman Lhoeb L.L.C.</i>	Lease No. 11111	Date <i>01-15-15</i>	
Lease <i>Clark</i>	Well # <i>8</i>		
Field Order # <i>2152</i>	Station <i>Pratt</i>	Casing <i>5 1/2</i>	Depth <i>3395</i>
Type Job <i>LNW 5 1/2 LS</i>	Formation	County <i>Sumner</i>	State <i>KS</i>
		Legal Description <i>2 31 3</i>	

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME		
Casing Size	Tubing Size	Shots/Ft		Acid	RATE	PRESS	ISIP	
<i>5 1/2</i>								
Depth	Depth	From	To	Pre Pad	Max		5 Min.	
<i>3395</i>								
Volume	Volume	From	To	Pad	Min		10 Min.	
<i>80.5</i>								
Max Press	Max Press	From	To	Frac	Avg		15 Min.	
Well Connection	Annulus Vol.	From	To		HHP Used		Annulus Pressure	
Plug Depth	Packer Depth	From	To	Flush	Gas Volume		Total Load	
<i>3381</i>								

Customer Representative <i>Tracy Black</i>	Station Manager <i>Kevin</i>	Treater <i>Pat / JDR</i>
---	---------------------------------	-----------------------------

Service Units	<i>33705</i>	<i>20920</i>	<i>70959</i>	<i>21010</i>		<i>92911</i>				
Driver Names	<i>Josh</i>		<i>Aaron Gibson</i>			<i>Joe</i>	<i>Pat E</i>			

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
<i>20:25</i>					<i>ON location / Safety Meeting</i>
					<i>Running 80 joints of 5 1/2 casing at 15.5 lb</i>
					<i>Centralizers on joint 1, 2, 3, 5, 7, 10, 12, 14, 15, 18, 21, 25</i>
					<i>Basket on 6 + 13 on collar</i>
<i>21:30</i>					<i>Start running casing</i>
<i>23:15</i>					<i>Casing on bottom</i>
<i>23:30</i>					<i>Circulate with rig</i>
<i>00:20</i>					<i>Hook up to pump to start job</i>
<i>00:25</i>	<i>200</i>		<i>5</i>	<i>5</i>	<i>H₂O spacer</i>
<i>00:26</i>	<i>200</i>		<i>24</i>	<i>5</i>	<i>Mix mud flush</i>
<i>00:30</i>	<i>200</i>		<i>5</i>	<i>5</i>	<i>H₂O spacer</i>
<i>00:40</i>	<i>200</i>		<i>60</i>	<i>5</i>	<i>Mix 250 sks of 50/150 P02 @ 14 lbs</i>
<i>00:55</i>			<i>A</i>	<i>A</i>	<i>Shut down clear pump + line</i>
<i>01:00</i>			<i>A</i>	<i>6 1/2</i>	<i>Release plug, start H₂O displacement w/200K</i>
<i>01:10</i>	<i>250</i>		<i>30</i> <i>30</i>	<i>6 1/2</i>	<i>Lift psi</i>
<i>01:25</i>	<i>700</i>		<i>70</i> <i>70</i>	<i>4</i>	<i>Slow rate</i>
<i>01:30</i>	<i>1500</i>		<i>80</i>	<i>0</i>	<i>Plug down</i>
					<i>Plug rat + mouse hole</i>
					<i>Job complete</i>
					<i>Thank You</i>
					<i>Patrick Egan / Joe Murphy</i>