

QUALITY WELL SERVICE, INC.

Federal Tax I.D. # 481187368


6344

Home Office 324 Simpson St., Pratt, KS 67124

Office 620-727-3410
Fax 620-672-3663

Rich's Cell 620-727-3409
Brady's Cell 620-727-6964

Date	03-31-15	Sec.	27	Twp.	32s	Range	12w	County	Barber	State	KS	On Location	12:30Am	Finish	3:15AM
Lease	Belle	Well No.	1	Location 281 #160 sec, 25, 2 1/4 w, 1/4 s/n to											
Contractor	Mavenick #106	Owner Griffin													
Type Job	Sur face	To Quality Well Service, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.													
Hole Size	12 1/4	T.D.	270	Charge To Griffin Management											
Csg.	8 5/8	Depth	270	Street											
Tbg. Size		Depth		City State											
Tool		Depth		The above was done to satisfaction and supervision of owner agent or contractor.											
Cement Left in Csg.	20'	Shoe Joint	N/A	Cement Amount Ordered 175sx class A + 2 1/2 gal + 3 1/2 cc											
Meas Line		Displace	15 1/2 BBLs Fresh	+ 1/4 # Flocel											
EQUIPMENT															
Pumptrk	8	No.	David F	Common 175											
Bulktrk	9	No.	David B Mike B	Poz. Mix											
Bulktrk		No.		Gel. 3											
Pickup		No.		Calcium 6											
JOB SERVICES & REMARKS				Hulls											
Rat Hole		Salt													
Mouse Hole		Flowseal 43.75													
Centralizers		Kol-Seal													
Baskets		Mud CLR 48													
D/V or Port Collar		CFL-117 or CD110 CAF 38													
Pipe on BHM, Break Circ, Pump Spacer,				Sand											
mix 175sx A 243 cement, Start Disp. w/				Handling 184											
Fresh H2O, wash up truck, Slow Rate, Stop				Mileage 10											
Pump at 15 1/2 BBLs total Disp, Shut in				FLOAT EQUIPMENT											
Cement Did Circ.				Guide Shoe											
				Centralizer											
				Baskets											
				AFU Inserts											
				Float Shoe											
				Latch Down											
				LMV 10											
				Service Supervisor											
				Pumptrk Charge Surface											
				Mileage 20											
				Tax											
				Discount											
				Total Charge											
X Signature	Paul G. Furner														



BASICSM
ENERGY SERVICES
PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61
P.O. Box 8613
Pratt, Kansas 67124
Phone 620-672-1201

FIELD SERVICE TICKET
1718 12406 A

DATE _____ TICKET NO. _____

DATE OF JOB: 04-06-15		DISTRICT: Pratt		NEW WELL <input checked="" type="checkbox"/> OLD WELL <input type="checkbox"/>		PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/>		CUSTOMER ORDER NO.:	
CUSTOMER: Pratt in Midway				LEASE: BGLLE		WELL NO.:			
ADDRESS:				COUNTY: BARBER		STATE: KAN			
CITY:				STATE:		SERVICE CREW: Sullivan, Egan, Branchy			
AUTHORIZED BY:				JOB TYPE: c/w 5" tubing					
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	AM	TIME
							4-6-15	PM	5:00
20920	45					ARRIVED AT JOB		AM	7:30
19918	20					START OPERATION		AM	2:00
						FINISH OPERATION		AM	2:45
						RELEASED		AM	3:19
						MILES FROM STATION TO WELL			35

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: *[Signature]*
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
CP 105	AA-2 cont	SK	200		3,400.00
CP 105	SAA-2 cont	SK	50		850.00
CR 102	Call Pipe	lb	63		233.10
CC 111	SALT	lb	1141		570.50
CC 112	C 3 R	lb	118		708.00
CC 115	C 44	lb	235		1,210.25
CC 201	G. 2000's	lb	1250		837.50
CF 607	LATCH down Plug & Baffle 5"	SA	1		400.00
PF 1251	Rate Fill Hobl Shoe	SA	1		360.00
CF 1651	Tool Joint	SA	5		550.00
PE 1901	BASKIT	SA	1		290.00
C 704	Clay mix	gal	5		175.00
C 121	Welds Flange	gal	500		750.00
E 100	Hydro oil	gal	35		157.50
E 101	Hydro Spot	gal	70		525.00
E 113	Bull Dog	TON	411		1,026.13
PE 205	Depth change 4000-5000	SK	1		2,570.00
CF 240	Welding - on string	SK	250		350.00
CF 508	Welding - on string	SK	1		230.00
5003	Service - open	SK	1		175.00
SUB TOTAL					15,337.98
CHEMICAL / ACID DATA:					
SERVICE & EQUIPMENT					%TAX ON \$
MATERIALS					%TAX ON \$
TOTAL					8,743.79

SERVICE REPRESENTATIVE: <i>[Signature]</i>	THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: <i>[Signature]</i>
FIELD SERVICE ORDER NO. _____	(WELL OWNER OPERATOR CONTRACTOR OR AGENT)

Customer <i>Griffin Energy</i>		Lease No.	Date	
Lease <i>BELLE</i>		Well #	<i>04-06-15</i>	
Field Order # <i>12406</i>	Station <i>PRATT KS</i>	Casing <i>5 1/2</i>	Depth	County <i>BARBER</i> State <i>KS</i>
Type Job <i>CNW 5 1/2 longstay</i>	Formation	Legal Description <i>27-32-12</i>		

PIPE DATA		PERFORATING DATA		FLUID USED	TREATMENT RESUME		
Casing Size	Tubing Size	Shots/Ft		Acid	RATE	PRESS	ISIP
<i>5 1/2</i>							5 Min.
Depth <i>4850</i>	Depth	From	To	Pre Pad	Max		
Volume <i>107</i>	Volume	From	To	Pad	Min		10 Min.
Max Press <i>2500</i>	Max Press	From	To	Frac	Avg		15 Min.
Well Connection <i>P.C.</i>	Annulus Vol.	From	To		HHP Used		Annulus Pressure
Plug Depth <i>4831</i>	Packer Depth	From	To	Flush	Gas Volume		Total Load

Customer Representative				Station Manager <i>David Scott</i>				Treater <i>Robert Johnson</i>			
Service Units	<i>27900</i>	<i>33709</i>	<i>20970</i>	<i>19826</i>	<i>19918</i>						
Driver Names	<i>Sullivan</i>	<i>Edwards</i>		<i>Brady</i>							

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
<i>7:30</i>					<i>on loc</i>
					<i>Run 5 1/2 30' csg.</i>
<i>1:00</i>					<i>CRISDI on Bottom</i>
<i>1:10</i>					<i>Hook by cnc</i>
<i>2:00</i>			<i>3</i>	<i>3.5</i>	<i>1st spacer</i>
			<i>12</i>		<i>2nd mud flush</i>
			<i>3</i>		<i>spacers</i>
			<i>#8</i>	<i>5</i>	<i>mix out 200K H₂O out @ 15:00</i>
					<i>cut mud & shut down wash pump & line</i>
					<i>Release Plug</i>
				<i>6</i>	<i>1st disp</i>
	<i>300</i>		<i>65</i>		<i>left</i>
				<i>4</i>	<i>2nd disp</i>
<i>2:45</i>	<i>1850</i>		<i>107 1/2</i>		<i>plug down</i>
			<i>7</i>	<i>2</i>	<i>plug AH of 20K</i>
			<i>7</i>		<i>plug out of 20K</i>
					<i>JOB COMPLETE</i>
					<i>Thank you</i>